

# ANNUAL SURVEYS.

42684

No. 116 Survey held at London Date, first Survey 17 July Last Survey 17 July 18 83  
 No. in Reg. Book. 116 on the BK Barossa Master H. J. Walker  
 Tonnage { Net 968 Built at Sunderland When built 1873 5  
 Gross 1019  
 Under Dk. 885 By whom built W. Pile & Co. Owners J. B. Walker  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock E. J. Dock  
 (State Name of Dock.)

Last Survey, No. 41583 Port of London

Classed 100 A-6.82

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of 3 lbs. 12 & 16 lb

Cables Paul & Co.

Hawsers and Warps

Standing and Running Rigging

*She is now in an efficient state and eligible to remain as before*  
*Inspected 21st June per Report No 257*

Committee's Minute

TUESDAY 24 JULY 1883

18

*Seaborn Martindale*

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

No. 116 Survey held at London Date, first Survey 17 July Last Survey 17 July 18 83

No. in Reg. Book. 116 on the BK Barossa

Master H. J. Walker

Year.

Month.

Tonnage { Net

Built at

When built

Gross

By whom built

Owners

Under Dk.

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Last Survey, No.

Port of

Classed

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18

Character assigned


Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

© 2021



Lloyd's Register

Foundation

LON 670-0549

(If a Steam Ship, state if a Report is also sent on the Machinery)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/83.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)