

REPORT of SURVEY for REPAIRS, &c.

42705

FRIDAY 10 AUGUST 1883

No.

No. in Survey held at
Reg. Book.

London

Date, first Survey

(No. of Visits)

(Received at London Office)

Last Survey

1883

221 on the *SS "Pelaw"*

Master

Scunbar

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

694

793

593

Built at

Sunderland

When built

1869

MONTH.

10

Owners

Commercial M^{rs} Co (L^{td})

Port belonging to

London

Residence

By whom built

J. Laing

Destined Voyage

Coaster

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Somekin dock ways

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 42156 Port

Low

Classed

95A1

1-83

S.S. Low No 3-82

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Society's Freeboard (if assigned) as painted on Ship

State dates of any letters respecting this case

*Through damage - 4 Beam frames at after part of Bridge house
Starboard side new. 2 wood Beams scarp'd. bulwarks set fair
2 bulwark stanchions repaired. one piece of main Rail and
one piece of Top pallet rail new - 3 planks of Bridge deck new
caulking of Bridge deck made good & main deck also*

Present Condition of the

Decks

Good

Transoms

Reck

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stems

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

3 Hs

Upper Deck Beams & Fastenings

Timbers of the Frame at the openings

Masts, Yards, &c.

from Deck

Lower Deck Beams & Fastenings

Ditto Ditto at other places

Condition, how ascertained

Good

Planksheers

Keelsons

Sails

Good

Sheerstrakes

Ceiling

Anchors

No. of *3 B. 15 + 2 H*

Topsides

Rudder

Cables

part seen Good

Wales

Copper (or Y.M.) When put on

Hawsers and Warps

Plank (Bottom) and Counter

not seen

Cement (if Iron Ship)

1869

Good

Standing & Running Rigging

Engine Room Skylights

Caulking of Bottom, Deck, & Waterways

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &c.

*As far as seen she appears in good condition
and in our opinion eligible to continue as Classed*

The Amount of Entry Fee £

16/8/83 Special £

Certificate (if required)

to be sent as per margin... .. £

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

received by me,

20 Aug 1883

Wm. E. Davey

Edward J. Tierney

Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 17 AUGUST 1883

95A1

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

LON 670-0580



© 2021

Lloyd's Register Foundation

(Insert Character precisely as in Register Book.)