

# ANNUAL SURVEYS.

42765

No. 188 Survey held at London Date, first Survey July 23 Last Survey July 30 1883  
(Received at London Office 29 AUGUST 1883)  
 No. in Reg. Book. on the Iron S.S. "Gulf of Suez" Master L. B. Hubbard  
(No. of Visits)  
 Tonnage Net 1014 Built at West Ham, London When built 1880 - 5  
Gross 1592  
N. 81799 Under Dk. 1439 By whom built W. Gray & Co Owners Greenock S.S. Co. (Ltd)  
 Port belonging to Greenock Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Millwall Dry Dock afloat Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 8274 Port of Greenock Classed 100 A 1  
 Present Condition of the Decks good Treenails good Rivets good  
 Waterways " Breasthooks and Stenson " Windlass and Capstan good  
 Comings " Transoms, Pointers, and Crutches " Pumps "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places not seen Masts, Yards, &c. "  
 Planksheers " Keelsons not seen Condition, how ascertained by observation  
 Sheerstrakes " Clamps and Shelves good Sails Sufficient  
 Topsides " Ceiling " Anchors, No. of 3 B, 1 S, 2 K  
 Wales " Rudder " Cables part seen on Deck good  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1880 Hawser and Warps Sufficient  
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging "  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock the bottom examined and recoated with paint, is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 28 AUGUST 1883  
 Character assigned 100 A 1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
(No. of Visits)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
Year. Month.  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_  
Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stenson \_\_\_\_\_ Windlass and Capstan \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_ Pumps \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_ Boats \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_ Masts, Yards, &c. \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_ Condition, how ascertained \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_ Sails \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_ Anchors, No. of \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_ Cables \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_ Hawser and Warps \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_ Standing and Running Rigging \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery) (The Surveyors are requested not to write on or below the space for Committee's Minute) (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/2/83.) (The Surveyors are requested not to write on or below the space for Committee's Minute)

(Insert Character precisely as in Register Book.) (Insert Character precisely as in Register Book.)

