

ANNUAL SURVEYS.

(Received at London Office, _____)

No. 41 Survey held at London Date, first Survey 13 Aug Last Survey 22 Aug 1883
 No. in Reg. Book. on the S Cairnbulg Master Murray (No. of Visits) _____
 Tonnage 1567 Built at Aberdeen When built 1874 3
1555 By whom built J Suthie & Co Owners W Suthie & Co
 Under Dk. 1487 Port belonging to Aberdeen Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens St & Afloat Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41899 Port of London

Classed 100A 10.82
SS Lon No 2-82.

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shells	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.		Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>

General Observations, Opinion as to Class, &c. Bottom & coated.
She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

FRIDAY 31 AUGUST 1883

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 533 Survey held at London Date, first Survey 23 July Last Survey 23 August 1883
 No. in Reg. Book. on the BK Glanpadarn Master A Roberts (No. of Visits) _____
 Tonnage 1082 Built at Sunderland When built 1877 12
1112 By whom built W Foxford & Son Owners S P Williams
 Under Dk. 1045 Port belonging to Carnarvon Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackhall St & Afloat Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5825 Port of Wales

Classed 100A 8.82
SS Cardiff No 1-82

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shells	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.		Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>

General Observations, Opinion as to Class, &c. Bottom & coated.
She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

FRIDAY 31 AUGUST 1883

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

4200-18907