

REPORT of SURVEY for REPAIRS, &c.

42788
1/9/83

No. 1061 in Survey held at LONDON Date, first Survey Aug 24 Last Survey Aug 26 1883
 Reg. Book. 1061 on the (Wood) Sailing Ship "SUFFOLK" (No. of Visits) 5 Master Byford
 TONNAGE under Tonnage Deck 832 Built at Northam When built 1857
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 975 Owners H. Ellis & Sons Port belonging to LONDON
 Crew Space, as per Rule
 Register Tonnage cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 975 By whom built Wigram Destined Voyage Mossu Bay
 If Surveyed Afloat or in Dry Dock Limehouse dry dock South Africa
 (State Name of Dock)
 Length of Poop - ft. Ditto, Forecastle - ft. Ditto, Raised Quarter Deck - ft.

Last Survey, No. 577 Port Rotterdam 4-82 - (FYM-3-82) Classed 13. A. 7 4-82
 REPAIRS, OR EXAMINATION AS PER RULE Rest. Lou. Sect 81-72
 Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship.

State dates of any letters respecting this case Re. Metallung.

This vessel placed in dry dock, old metal slightly wrinkled, stripped off. bottom examined, caulked, & tested and resheathed with yellow metal on feet.

Present Condition of the	Good	Treenails	Good	Windlass and Capstan	good
Decks	Good	Good	Good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stenson	"	Pumps	2
Comings	"	Transoms, Pointers, and Crutches	"	Boats	4
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from deck.
Planksheers	"	Keelsons	"	Sails	2 suits good
Sheerstrakes	"	Clamps and Shelves	"	Anchors	No. of 3B-18-2K
Topsides	"	Ceiling	"	Cables	where seen good
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or Y.M.) on feet When put on <u>Aug 83</u> (State if on feet)	"	Standing & Running Rigging	"
Engine Room Skylights	good	Cement (if Iron Ship)	"		
Coal Bunker, Openings, Lids, &c.		Caulking of Bottom, Deck, & Waterways	good		
Scuppers	good				
Cargo and Main Hatchways	good				
Hatches	good				

General Observations, Opinion as to Class, &c. *This vessel appears in a sound and efficient condition and eligible in my opinion to remain as classed. It is submitted that the vessel be marked in the Register Book. FYM. 8-83.*

The Amount of Entry Fee ... £ : : received by me, Edward John Currier
4/9/83 Special ... £ 2 : 2 : 0 11/9 1883
 Certificate (if required) to be sent as per margin... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute
 Character assigned
 4 SEPTEMBER 1883
 Lloyd's Register of British and Foreign Shipping



If a Steam Ship, state whether or not a Report is also sent on the Machinery

Insert Cl. precisely as in Register Book.

The Surveyors are requested not to write on or below the space for Committee's Minute.

L200-1199