

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 11/9/83)

No. 312 Survey held at Boulogne Date, first Survey Aug 25th Last Survey 1883
 Reg. Book. 312 on the Iron Screw Steamer The Mc Intyre Master —
 TONNAGE under Tonnage Deck 935 925
 Ditto of Spar Deck, or Awaiting Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 991
 Crew Space, as per Rule
 Register Tonnage, ton on Beam
 Engine Room
 Reg. Tons as St' mer, out on Bm. 925
 Built at Newcastle When built 1863 - 8
 Owners J Fenwick & Sons Port belonging to Boulogne
 Residence
 By whom built Palmer's Coy Destined Voyage
 If Surveyed Afloat or in Dry Dock Quirk's Dry Dock
 (State Name of Dock)
 Length of Poop — ft. Ditto, Forecastle — ft. Ditto, Raised Quarter Deck 53 ft.
 Last Survey, No. 41687 Port Low
 REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.
 State dates of any letters respecting this case — Damage Repairs
 Classified 90. A. 7.
S. S. Low 103-80
Low 8-80
 Society's Freeboard (if assigned) as painted on Ship

This vessel has recently been under survey by Mr Martindale, bottom painted &c. On Friday Aug 24th when proceeding "light" to sea ran over the sunken wreck of the Government Steamer "Thames", off Woolwich Arsenal, the vessel was placed in dry dock the bottom examined & the painting where rubbed renewed

Present Condition of the					
Decks	<i>good</i>	Trunnels <i>Ports</i>	<i>good</i>	Windlass and Capstan	<i>good</i>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<i>from a/c</i>
Planksheers	"	Keelsons	"	Sails	<i>good</i>
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	<i>3 B-18-2 K</i>
Topsides	"	Ceiling	"	Cables	<i>when run good</i>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or Y.M.) When put on	"	Standing & Running Rigging	"
		(State if on Felt.)	"		
		Cement (if Iron Ship)	"		
		Caulking of Bottom, Deck, & Waterways	"		
Engine Room Skylights	<i>good</i>	Coal Bunker, Openings, Lids, &c.	<i>good</i>	Scupper	<i>good</i>
General Observations, Opinion as to Class, &c.				Cargo and Main Hatchways	<i>good</i>
				Hatches	<i>good</i>

General Observations, Opinion as to Class, &c.

This vessel appears in a perfectly sound and efficient condition, and in my opinion eligible to remain as classed.

Senhouse Martindale

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ : : 188

Certificate (if required) } £ : :
 to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

B. S. 8 83

4 SEPTEMBER 1883

Edward John Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
 Foundation