

ANNUAL SURVEYS.

42807
19/83

No. 159 Survey held at London Date, first Survey 20th August Last Survey 28 August 1883
 No. in Reg. Book. on the SS Samuel Laing Master H. Knight
 Tonnage 477 Net 609 Gross 572 Under Dk. Built at Newcastle When built 1854
 By whom built Palmer & Co Owners J. Jenrick & Son
 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Portion Victoria St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5308 Port of Kull
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom is coated and eligible to remain as classed.

Classed 80 Years assigned 5.83 Character in Register Book SS M-3-75 SS Lan M 281

Senhouse Martindale

Committee's Minute FRIDAY 7 SEPT 1883
 Character assigned B.S. 80A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 159 Survey held at London Date, first Survey 20th August Last Survey 28 August 1883
 No. in Reg. Book. on the SS Samuel Laing Master H. Knight
 Tonnage 477 Net 609 Gross 572 Under Dk. Built at Newcastle When built 1854
 By whom built Palmer & Co Owners J. Jenrick & Son
 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Portion Victoria St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5308 Port of Kull Classed 80 Years assigned 5.83 Character in Register Book SS M-3-75 SS Lan M 281

Present Condition of the Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom is coated and eligible to remain as classed.

Committee's Minute
 Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)



0500-18907