

# Report of Survey for Repairs of Engines and Boilers.

42809  
21-8-83

No. 293 (Received at London Office, 21-8-83)  
 No. in Reg. Book. 293 Survey held at London Date, first Survey 16<sup>th</sup> August Last Survey 17 August 1883  
 on the Machinery of the Screw Steamer "Florida" (Number of Visits 2)  
 Tonnage, Gross 3138 Built at Newcastle When built 1882  
 Ditto, Net 2044 Owners Nelson Donkin & Co. Port belonging to London  
 Diameter of Cylinder 40 & 74 Engines made by N. E. Marine Co L<sup>d</sup> When made 1882  
 Length of Stroke 54 Boilers made by Do When made 1882  
 Pressure of Steam 90 If Surveyed Afloat or in Dry Dock Albert Dock (State name of Dock.)  
 Registered Horse Power 350 Classed 100 A 1  
 Last Survey No. 5293 Port Stull L.M.B. 183.

Particulars of Repairs and Examination of furnaces of main boilers  
(State cause of Repairs.)  
 Found them slightly flattened and out of shape, they have now been satisfactorily set to the true circular form.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is now in good order and safe working condition and eligible in my opinion to remain as classed

Entry or Registering Fee... 6/1/83 £ : :  
 Survey Fee (per Section 28) ... £ 1 : 0 : 0 received by me, 7/7/83  
 Certificate (if required) ... £ : : 10/9 1883  
to be sent as per margin.

(Travelling Expenses, if any, £ )  
 Committee's Minute  
 Assigned

W. and P. Jones  
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

FRIDAY 7 SEPT 1883 188



© 2021

Lloyd's Register Foundation

(State if Report is ass... Hull of th...  
 (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in the Register Book.

9500-149207