

# REPORT of SURVEY for REPAIRS, &c.

42815  
6.8.83

No. in Survey held at London Date, first Survey Aug 3/83 Last Survey Sept 4/83 1883  
 Reg. Book. 468 on the Iron Screw Steamer Homer (No. of Visits) Master Puncher  
 TONNAGE under Tonnage Deck 1126 Built at S. Shields When built 1881  
 Ditto of Spar Deck, or Awning Deck Owners Dick & Page Port belonging to London  
 Ditto of Poop Residence  
 Ditto of Raised Qr. Dk. By whom built J. Readhead & Co Destined Voyage Leith  
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock (State Name of Dock) Carters, Millwall  
 Gross Tonnage 1384 Reg. Tons as St' mer, cut on Bm. 892  
 Engine Room Length of Poop 50 ft. Ditto, Forecastle 25 ft. Ditto, Raised Quarter Deck 95 ft.

Last Survey, No. 16662 Port Shields 3-83 Classed 100.A.1  
 REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated.  
 State dates of any letters respecting this case

Damage Repairs  
Rudder lifted, broken band, taken off and renewed new upper pinche of steel the remainder of the pinches being steel bushed; the covering plate to rudder bank on counter, and the deck casting unbolted, for moving rudder, replaced, 3 loose rivets in the band of stopper. cut out & renewed also 2 in the stern post. & the edges of the plates caulked where struck by propeller. blades men falling off. One plate of the starboard side of the funnel, and one stiffening angle iron taken off (to ship old fair sharp and reship new,) replaced and permitted. Bottom painted.

Present Condition of the		Decks		Good		Freenuts Rants		Good		Windlass and Capstan		Good	
Waterways	"	Good	"	Good	"	Breasthooks and Stems	"	Good	"	Pumps	2	"	"
Comings	"	"	"	"	"	Transoms, Pointers, and Crutches	"	"	"	Boats	3	"	"
Upper Deck Beams & Fastenings	"	"	"	"	"	Timbers of the Frame at the openings	"	"	"	Masts, Yards, &c.	"	"	"
Lower Deck Beams & Fastenings	"	"	"	"	"	Ditto Ditto at other places	"	"	"	Condition, how ascertained	from deck	"	"
Planksheers	"	"	"	"	"	Keelsons	"	"	"	Sails	2 sets	Good	"
Sheerstrakes	"	"	"	"	"	Clamps and Shelves	"	"	"	Anchors	No. of 3/8-18-21	"	"
Topsides	"	"	"	"	"	Ceiling	"	"	"	Cables	what run	Good	"
Wales	"	"	"	"	"	Rudder	"	"	"	Hawsers and Warps	7	"	"
Plank (Bottom) and Counter	"	"	"	"	"	Copper (or Y.M.) When put on	"	"	"	Standing & Running Rigging	"	"	"
Engine Room Skylights	good	Coal Bunker, Openings, Lids, &c.	good	Scuppers	good	Cement (if Iron Ship)	8/	"	"	Cargo and Main Hatchways	good	Hatches	good
General Observations, Opinion as to Class, &c.													

This vessel having been placed in dry dock, bottom examined, &c and she appears in a sound & efficient condition, and eligible in my opinion to continue as classed.

The Amount of Entry Fee ... 1/9/83 : : received by me, 44/8  
 Special ... 1/1/83 : : 1883  
 Certificate (if required) to be sent as per margin... } £ : 5 :  
 (Travelling Expenses, if any, £ )  
 Committee's Minute TUESDAY 11 SEPT 1883  
 Character assigned 100  
 Edward John Turner  
 Surveyor to Lloyd's Register of British and Foreign Shipping.