

ANNUAL SURVEYS.

42823

No. 187 Survey held at London Date, first Survey July 30th Last Survey July 30th 1883
 No. in Reg. Book. on the Iron S.S. "Cape Clear" Master Henderson
 Tonnage { Net 1501 Built at Greenock When built 1881 - 9
 { Gross 2350
 { Under Dk. 2334 By whom built R. Steele & Co Owners A. Lyle & Sons
 Port belonging to Greenock Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Repaired Green Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42078 Port of London Classed 100 A 1
 Present Condition of the Decks good Treenails good Rivets good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Quanted When put on 1881
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock the bottom examined and recoated with paint, is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute _____ TUESDAY 11 SEPT 1883
 Character assigned 100 A 1 J.B.W.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____
 { Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18

(If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

