

## ANNUAL SURVEYS.

42874

No. 59 Survey held at London Date, first Survey 4 Sept Last Survey 11 Sept 1883  
(No. of Visits 1)  
No. in Reg. Book. on the S S James Joyce Master J. Pennington  
Tonnage { Net 441 Built at Newcastle When built 1863 Year. 5 Month. 5  
Gross 702  
Under Dk. 645 By whom built Palmer Owners J. Pennington  
Port belonging to London Destined Voyage Lyne  
If Surveyed Afloat or in Dry Dock Penton Victoria Society's Freeboard (if assigned) as painted on Ship.  
(State Name of Dock.)  
Last Survey, No. 41663 Port of London

Present Condition of the  
Decks Good Treenails Rivets Good  
Waterways 1 Breasthooks and Stemson 1  
Comings 1 Transoms, Pointers, and Crutches 1  
Upper Deck Beams & Fastenings 1 Timbers of the Frame at the Openings 1  
Lower Deck Beams & Fastenings 1 Ditto ditto at other places 1  
Planksheers 1 Keelsons 1  
Sheerstrakes 1 Clamps and Shelves 1  
Topsides 1 Ceiling 1  
Wales 1 Rudder 1  
Plank (Bottom) and Counter 1 Copper or Y.M. Coated When put on new  
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches 1  
General Observations, Opinion as to Class, &c. Bottom to be coated.  
She is now in an efficient state  
and eligible to remain as classed.

Lighthouse Martindale

Committee's Minute FRIDAY 21 SEPT 1883  
Character assigned B.S. 9-83  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

No. 59 Survey held at London Date, first Survey 4 Sept Last Survey 11 Sept 1883  
(No. of Visits 1)  
No. in Reg. Book. on the S S James Joyce Master J. Pennington  
Tonnage { Net 441 Built at Newcastle When built 1863 Year. 5 Month. 5  
Gross 702  
Under Dk. 645 By whom built Palmer Owners J. Pennington  
Port belonging to London Destined Voyage Lyne  
If Surveyed Afloat or in Dry Dock Penton Victoria Society's Freeboard (if assigned) as painted on Ship.  
(State Name of Dock.)  
Last Survey, No. 41663 Port of London Classed 18  
Present Condition of the  
Decks Good Treenails Rivets Good  
Waterways 1 Breasthooks and Stemson 1  
Comings 1 Transoms, Pointers, and Crutches 1  
Upper Deck Beams & Fastenings 1 Timbers of the Frame at the Openings 1  
Lower Deck Beams & Fastenings 1 Ditto ditto at other places 1  
Planksheers 1 Keelsons 1  
Sheerstrakes 1 Clamps and Shelves 1  
Topsides 1 Ceiling 1  
Wales 1 Rudder 1  
Plank (Bottom) and Counter 1 Copper or Y.M. Coated When put on new  
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches 1  
General Observations, Opinion as to Class, &c. Bottom to be coated.  
She is now in an efficient state  
and eligible to remain as classed.

Committee's Minute FRIDAY 21 SEPT 1883  
Character assigned B.S. 9-83  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18





© 2021

Lloyd's Register  
Foundation