

# ANNUAL SURVEYS.

42902

SATURDAY 22 SEPT 1883

No. 33 Survey held at London Date, first Survey 10 Sept Last Survey 11 Sept 1883  
 No. in Reg. Book. on the Iron S.S. "York" Master Oliver  
 Net 456 Built at Newcastle When built 1865 Month. 12  
 Tonnage Gross 709 Under Dk. 676 By whom built Marshall Bros Owners W. Rawson & J. Robinson  
 Port belonging to Hull Destined Voyage Middlesboro'  
 If Surveyed Afloat or in Dry Dock Linehouse Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41237 Port of Low Classed A1 3.82  
 Present Condition of the Decks Good Treanails Rivets Good S.S. Hull No 3.76  
 Waterways --- Breasthooks and Stenson --- S.S. Low No 1.80  
 Comings --- Transoms, Pointers, and Crutches --- Windlass and Capstan Good  
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Pumps 3 No  
 Lower Deck Beams & Fastenings --- Ditto ditto at other places --- Boats 3 No  
 Planksheers --- Keelsons --- Masts, Yards, &c. ---  
 Sheerstrakes --- Clamps and Shelves --- Condition, how ascertained from Deck  
 Topsides --- Ceiling --- Sails Good  
 Wales --- Rudder --- Anchors, No. of 3 B. 15 + 2 K  
 Plank (Bottom) and Counter --- Copper or Y.M. --- When put on --- Cables part seen Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.  
Rudder braces riveted & Bottom repainted  
She is now in good condition and eligible in my opinion to remain as Classed

Committee's Minute FRIDAY 23 SEPT 1883  
 Character assigned --- Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18  
42903

No. 1060 Survey held at London Date, first Survey --- Last Survey 18 Sept 1883  
 No. in Reg. Book. on the Iron S.S. "Crosser" Master Longley  
 Net 1323 Built at Stockton When built 1882 Month. 5  
 Tonnage Gross 2035 Under Dk. 1939 By whom built Richardson Duck Owners Shaw, Busby & Co  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Linekilm Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42280 Port of Low Classed 100A1  
 Present Condition of the Decks Good Treanails Rivets Good 2.83  
 Waterways --- Breasthooks and Stenson --- Windlass and Capstan Good  
 Comings --- Transoms, Pointers, and Crutches --- Pumps 4  
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Boats 4  
 Lower Deck Beams & Fastenings --- Ditto ditto at other places --- Masts, Yards, &c. ---  
 Planksheers --- Keelsons --- Condition, how ascertained from Deck  
 Sheerstrakes --- Clamps and Shelves --- Sails Good  
 Topsides --- Ceiling --- Anchors, No. of 3 B. 15 + 2 K  
 Wales --- Rudder --- Cables part seen Good  
 Plank (Bottom) and Counter --- Copper or Y.M. --- When put on --- Hawsers and Warps 6 No St. Chain  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.  
Bottom recoated. Some new rivets in back of Rudder. She is now in good condition and in my opinion may continue as Classed

Committee's Minute FRIDAY 23 SEPT 1883  
 Character assigned --- Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18  
100A1

(If a Steam Ship, state if a Report is also sent on the Machinery) (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Form No. 3 for Annual Survey, when there are no repairs, 2010-18/5/83.)

(Insert Character precisely as in Register Book.) LONBFL-0164

