

ANNUAL SURVEYS.

43005

THURSDAY 20 SEPT 1883

No. 25 Survey held at London Date, first Survey 25 Augus Last Survey 18 Sept 1883
 No. in Reg. Book. on the SS Dorunda Master Templeton
 Tonnage { Net 1943 Built at Dumbarton When built 1875 Month. 10
 Gross 2977
 Under Dk. 2920 By whom built W Penny Bro Owners S Macneil & P Penny
 Port belonging to Glasgow Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Albert by W Vaper Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42130 Port of Low

Classed 100 A1 7.82
SS Lin No. 179.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & Coated

She is now in an efficient state and eligible to remain as classed.

TUESDAY 2 OCTOBER 1883

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 25 Survey held at London Date, first Survey 25 Augus Last Survey 18

No. in Reg. Book. on the SS Dorunda Master Templeton
 Tonnage { Net 1943 Built at Dumbarton When built 1875 Month. 10
 Gross 2977
 Under Dk. 2920 By whom built W Penny Bro Owners S Macneil & P Penny
 Port belonging to Glasgow Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Albert by W Vaper Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42130 Port of Low


Classed 100 A1 7.82
SS Lin No. 179.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & Coated

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

ANNUAL SURVEYS

Admiral

No.	Ship	Surveyed at	When built	When surveyed	Classed	Remarks
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100



© 2021
Lloyd's Register
Foundation