

REPORT of SURVEY for REPAIRS, &c.

No.

(Received at London Office,

3 OCTOBER 1883

No. in Survey held at

London

Date, first Survey 19 Sept Last Survey 28th Sept 1883,

Reg. Book,

on the

SS Grappler

(No. of Visits 3 times to the River Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

734

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

868

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St men, cut on Bm.

498

Built at

Sunderland

When built

1880

Owners

West India & Panama Tel & Port belonging to London

Residence

By whom built

Saing

Destined Voyage

West Indies

If Surveyed Afloat or in Dry Dock River new West India.

(State Name of Dock)

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Last Survey, No. 2609/Port

Iron

Classed 100 A. S. 80

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Society's Freeboard (if assigned) as painted on Ship

State dates of any letters respecting this case

Small Damage Repair. A small hole in one of the Port Bow plates has had a substantial doubling plate put over it.

Steam Anchor supplied

7-1-14 Tested to 9-11-2-7 River near Testing Machine dated April 13-1883

Signed J Hartnup

Present Condition of the

Decks

Good

Treenails Rivets

Good

Windlass and Capstan

Good

Waterways

"

Breasthooks and Stemson

"

Pumps

"

Comings

"

Transoms, Pointers, and Crutches

"

Boats

"

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the openings

"

Masts, Yards, &c.

"

Lower Deck Beams & Fastenings

"

Ditto Ditto at other places

"

Condition, how ascertained

From the

Planksheers

"

Keelsons

"

Sails

Good

Sheerstrakes

"

Clamps and Shells

"

Anchors No. of 3 Nos. 12 & 14 lbs

Topsides

"

Copper (or Y.M.) When put on

"

Cables Parton the

Good

Wales

"

Cement (if Iron Ship)

"

Hawsers and Warps

"

Plank (Bottom) and Counter

"

Caulking of Bottom, Deck, & Waterways

"

Standing & Running Rigging

"

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

"

General Observations, Opinion as to Class, &c.

She is now in an efficient state and eligible to remain as classed.

Surveyor 1-1

Senhouse Martindale

The Amount of Entry Fee ... £ ...

5/10 23 Special ... £ 1 : 1 : 7

received by me,

11/10 1883

Certificate (if required)

to be sent as per margin... £ : 5 : 3

Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £ ...)

Committee's Minute

FRIDAY 5 OCT 1883

Character assigned

1000 9, 80

1000 9, 80

TRM

© 2021

Lloyd's Register Foundation