

# ANNUAL SURVEYS.

43060

TUESDAY 16 OCT 1883

(Received at London Office)

No. 30 Survey held at London Date, first Survey 9<sup>th</sup> Oct Last Survey 10<sup>th</sup> October 1883  
(No. of Visits 2)  
 No. in Reg. Book. on the Iron Sailing Barque "Umzinto" Master Nurse  
 Tonnage Net 280 Built at Sunderland When built 1871 Month. 10  
Gross 304  
Under Dk. 265 By whom built W. Pile & Co. Owners Bullard & King  
 Port belonging to London Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock Fountain dry dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41693 Port of Low Low. Classed 100 A.1  
Years assigned. 7.82 Character in Register Book.  
 Present Condition of the Decks Good rivet Treenails Good Sp. S.S. W<sup>2</sup>-79  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has been in dry dock, the bottom repainted. the lower pintle of rudder has been renewed the vessel appears in a fit and efficient condition, and in my opinion is eligible to remain as classed

Committee's Minute FRIDAY 19 OCT 1883  
 Character assigned 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping. H. Hand  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
(No. of Visits \_\_\_\_\_)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_  
Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)  
 Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. \_\_\_\_\_ Character in Register Book.  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (Form No. 3 for Annual Survey, when there are repairs, 4000-18/5/83.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)

