

ANNUAL SURVEYS.

43073
FRIDAY 5 OCT 1883

No. 386 Survey held at London Date, first Survey 22nd Sept Last Survey 22nd Sept 1883
No. in Reg. Book. on the Iron S.S. "Joseph Rickett" Master P. Lockerton
449 Net 717 Gross 542 Under Dk. 542 Built at Kinghorn When built 1879 2
Tonnage By whom built Key & Son Owners Gamma & Carter
Port belonging to London Destined Voyage Coaster
If Surveyed Afloat or in Dry Dock Union Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42658 Port of London
Present Condition of the
Decks Good Freemains Rivets Good
Waterways Good Breasthooks and Stenson Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shells Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 1879
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, & Scuppers Good Cargo and Main Hatchways Good
General Observations, Opinion as to Class, &c. Good Hatches Good

Classed GOA 1 7.83
S.S. London 1.83

One plate of Quarter Deck set fair - bottom
recoated she is now in good condition and in my opinion
eligible to continue as Classed

Committee's Minute

TUESDAY 23 OCT 1883

Character assigned

Will^m C. Davey

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 15 Survey held at London Date, first Survey and Last Survey 2nd Oct 1883
No. in Reg. Book. on the Iron S.S. "Valencia" Master R. Roberts
344 Net 571 Gross 411 Under Dk. 411 Built at Port Glasgow When built 1880 10
Tonnage By whom built H. Murray & Co Owners J. Goodyear & Co
Port belonging to Liverpool Destined Voyage Barcelona via Swansea
If Surveyed Afloat or in Dry Dock Linehouse Society's Freeboard (if assigned) as painted on Ship 1" 2"
(State Name of Dock.)

Last Survey, No. 42064 Port of London
Present Condition of the
Decks Good Freemains Rivets Good
Waterways Good Breasthooks and Stenson Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shells Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 1880
Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, & Scuppers Good Cargo and Main Hatchways Good
General Observations, Opinion as to Class, &c. Good Hatches Good

Classed 100A 1
12.82

Bottom painted. She is now in good con-
dition and in my opinion eligible to continue as Classed

Committee's Minute

TUESDAY 23 OCT 1883

Character assigned

Will^m C. Davey

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON 671-0254