

REPORT of SURVEY for REPAIRS, &c.

43109

(Received at London Office.)

No. 367 in Survey held at LONDON Date, first Survey Oct 8 Last Survey Oct 9 1883
 Reg. Book. on the Iron Screw Steamer "GLENARON" Master DONALDSON
 TONNAGE under Tonnage Deck 2696 Built at Glasgow When built 1881 - - 2
 Ditto of Spar Deck, or Awning Deck Owners McEwen & Co Port belonging to Glasgow
 Ditto of Poop Residence LONDON
 Ditto of Raised Qr. Dk. By whom built LONDON Glas Ship Bldg Co Destined Voyage China
 Ditto of Houses on Deck Gross Tonnage 2985
 Ditto of Forecastle # Surveyed Afloat in Dry Dock Rowrie's Cubitt Town
 Crew Space, as per Rule Register Tonnage, cut on Beam Reg. Tons as St' mer, cut on Bm. 1936
 Length of Poop 49 ft. Ditto, Forecastle 50 ft. Ditto, Raised Quarter Deck 70 ft.
 Last Survey, No. 42299 Port LON Classed 100 A.1
 REPAIRS, OR EXAMINATION AS PER RULE ANNUAL SURVEY Society's Freeboard (if assigned) as painted on Ship
 Cause of Repairs to be clearly stated. State dates of any letters respecting this case AND FREE BOARD.

The vessel was placed in dry dock the bottom examined scraped and painted,

The L.R. Freeboard Marks assigned viz 6"0" in salt water & 5"7" in fresh water have been set off from a deck line levelled out from the top of deck at gutter waterway Margin plank, which is one inch higher at side than if extended down with round of beam to the side, it has been requested that all the marks be placed one inch lower, but the vessel has since sailed without the correction having been made.

Present Condition of the Decks	Good	Treenails	Rusts where seen	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stems	"	"	Pumps	4
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	6
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from deck
Plank sheers	"	Keelsons	"	"	Sails	1 Suit good
Sheerstrakes	"	Clamps and Shelves	Strangers	"	Anchors	No. of 3 2-15-216
Topsides	"	Ceiling	"	"	Cables	complete
Wales	"	Rudder	"	"	Hawsers and Warps	sufficient
Plank (Bottom) and Counter	"	Copper (on Yr. or Fe) When put on	"	"	Standing & Running Rigging	good
Engine Room Skylights	good	Cement (if Iron Ship)	Good	"	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	good	Caulking of Bottom, Deck, & Waterways	"	"	Hatches	good
Scuppers	good					

General Observations, Opinion as to Class, &c.
 The vessel appears in a sound and efficient condition and eligible in my opinion to remain as classed.

The Amount of Entry Fee ... £ 3 : : received by me,
 Special ... £ 3 : : 188
 Certificate (if required) to be sent as per margin... } £ : :

J. W. Miles.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £)
 Committee's Minute TUESDAY 6 NOV 1883
 Character assigned

Lake ...
J. W. Miles



© 2021 Lloyd's Register Foundation

is also at on the Machi

If a Steam Ship,

[Form No. 2 for Repairs.—1,000—2/788.]
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

2620-149207