

# REPORT of SURVEY for REPAIRS, &c.

43117

(Received at London Office)

NOV 6 NOV 1883

No. in Reg. Book. 41 on the Iron screw steamer Galicia Date, first Survey 31<sup>st</sup> Oct<sup>r</sup> Last Survey 31<sup>st</sup> Oct<sup>r</sup> 1883

Master G. Robinson  
 TONNAGE under Tonnage Deck 694  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Deck  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 794  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St<sup>r</sup>mer, cut on Bm. 499

Built at Hartlepool When built 1866 MONTH 4  
 Owners J. Hall Jr & Co Port belonging to London  
 Residence  
 By whom built Richardson & Duck Destined Voyage Lisbon  
 If Surveyed Afloat or in Dry Dock London Docks  
 (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
 Last Survey, No. 42761 Port Lisbon S. S. Hpl. No. 3-80 Classified A. 1.  
 Years assigned. Character in Register Book.

REPAIRS, OR EXAMINATION AS PER RULE  
 Cause of Repairs to be clearly stated. Freeboard  
 State dates of any letters respecting this case

The freeboard assigned by the committee for this vessel - viz. 2" salt water and 2" 0 1/2" fresh water, has been marked on both sides of the vessel, and examined and found correct.

Note - This vessel has a sheathing of 1 1/2" on Upper Deck, nearly the whole length, and the above freeboard has been set off from the top of same.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper (or Y.M.) When put on (State if on Felt.)	Standing & Running Rigging
Engine Room Skylights	Cement (if Iron Ship)	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways	Hatches
Scuppers		

General Observations, Opinion as to Class, &c.

The Amount of Entry Fee ... £ : : received by me, }  
 Special ... £ : : 188 }  
 Certificate (if required) } £ : :  
 to be sent as per margin... }

*Henry Hand*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £ )  
 Committee's Minute FRIDAY 9 NOV 1883  
 Character assigned Note freeboard



[Form No. 2 for Repairs, -1,000-27/83.]

[Insert Character precisely as in Register Book.]

LON 671-0299