

Report of Survey for Repairs of Engines and Boilers.

No. 43165 (Received at London Office, FRIDAY 7 NOV 1893)
 No. in Reg. Book. Survey held at London Date, first Survey 12th Nov^r Last Survey 12. Nov^r 1883

245 on the Machinery of the Screw Steamer "Vossan" (Number of Visits one)

Tonnage, Gross 1869 Built at Newcastle When built 1876
 Ditto, Net 1211 Owners Glover Bros. Port belonging to Newcastle
 Diameter of Cylinder 32" 62 Engines made by Black Hawthorn & Co. When made 1876
 Length of Stroke 36" Boilers made by Do - Do When made 1876
 Pressure of Steam 65 lbs. If Surveyed Afloat or in Dry Dock mill wall wet D.R. Character in Register Book. 100 A1
 Registered Horse Power 180 (State name of Dock.) Classed 9.83
 Last Survey No. 42878 Port Low Im b. 6.81

Particulars of Repairs and Examination Annual Survey of boilers + crank shaft
 (State cause of Repairs.)

Examined the main boilers internally + externally and found them in good condition.
Examined the crank shaft & found the mark in number three bearing had not altered since the last survey of machinery.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is now in good order and safe working condition and eligible in my opinion to have the notification B.S. 11.83. renewed subject to the resurvey of boilers as per Rule and the crank shaft in 12 months from the present date.

Entry or Registering Fee... £ — : — :
 Survey Fee (per Section 28) 21/11/83 £ 1 : 1 : 0 received by me, David James
 Certificate (if required) ... £ : : : 1884
 to be sent as per margin.
 (Travelling Expenses, if any, £)

Committee's Minute TUESDAY 20 NOV 1893 188

Assigned Note crank shaft

B.S. 11.83

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation

LON 671-0358