

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, THURSDAY 22 NOV 1883)

No. 598 on the Machinery of the S. P. Lombard. (Number of Visits 2)

No. in Reg. Book. 598 Survey held at London Date, first Survey 7 Nov Last Survey 8 Nov 1883

Tonnage, Gross <u>1750</u>	Built at <u>Newcastle</u>	When built <u>1877</u>
Ditto, Net <u>1132</u>	Owners <u>T. H. Davison</u>	Port belonging to <u>London</u>
Diameter of Cylinder <u>32</u> <u>62</u>	Engines made by <u>R. & W. Hawthorn</u>	When made <u>1877</u>
Length of Stroke <u>36</u>	Boilers made by	When made <u>1877</u>
Pressure of Steam <u>40</u>	If Surveyed Afloat or in Dry Dock	Classed <u>100 A1</u>
Registered Horse Power <u>160</u>	(State name of Dock.)	Character in Register Book. <u>2.82</u>
Last Survey No.	Port	<u>L.M.P. 1.82</u>

Particulars of Repairs and Examination Repairs to Propeller
(State cause of Repairs.)
Examined sea-cocks & connections & found them

good.
The Propeller had been removed & refitted.
The boilers were to have been opened out on the 8th
Nov. On that day no engineers were on board. As the
vessel has to remain in Cardiff for 7 or 8 days the Sur-
veyors of that port have been informed of the vessel's
departure for that port

General Observations, Opinion, and Recommendation:— As far as seen the
machinery of this vessel appears to be in a safe working
condition and is in my opinion eligible to remain
as classed


It is submitted that this vessel is eligible to remain as classed
J.M. 21/11/83

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : — received by me,
 Certificate (if required) ... £ : : 188
(The Surveys are requested not to write on or below the space for Committee's Minute.)
(Travelling Expenses, if any, £)

C. J. Stromeier
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

FRIDAY 23 NOV 1883 188

Committee's Minute
 Assigned



© 2021 Lloyd's Register Foundation

Form No. 9—3000, 20/5/82. [The Surveys are requested not to write on or below the space for Committee's Minute.]

Insert Character precisely as in the Register Book.

9430-149207