

ANNUAL SURVEYS.

43183

(Received at London Office, 13 NOV 1883)

No. 39 Survey held at LONDON Date, first Survey Nov 3rd Last Survey Nov 7th 1883
 No. in Reg. Book. on the Iron Screw Steamer OCEAN KING Master Murray
 Tonnage Net 623 Built at Sunderland When built 1863 - 6
Gross 955 By whom built Pine Hay & Co Owners B. B. Wake
Under Dk. 854 Port belonging to LONDON Destined Voyage (not fixed)
 If Surveyed Afloat or in Dry Dock Repairs dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 11960 Port of LONDON Classed 95 A.I.
 Present Condition of the Decks Good Treenails Good Rivets where seen Good
 Waterways " Breasthooks and Stemson " Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches " Pumps 2
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats 3
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Masts, Yards, &c. "
 Planksheers " Keelsons " Condition, how ascertained from deck
 Sheerstrakes " Clamps and Shelves strung Sails well found
 Topsides " Ceiling " Anchors, No. of 3 B - 1 S - 2 K.
 Wales " Rudder " Cables complete
 Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 1863 Hawser and Warps sufficient
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock the bottom examined scraped and painted, the Rudder lifted & painted, false pipe on Starboard side renewed. The vessel now appears in a sound and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 23 NOV 1883
 Character assigned 95 A.I. Edward John Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Net Built at When built
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship
 Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)

(Insert Character precisely as in Register Book.) (Insert Character precisely as in Register Book.)

Ocean King

Handwritten notes in cursive script, likely a signature or title, located at the top left of the page.

Handwritten notes in cursive script, likely a signature or title, located at the top left of the page.

Handwritten notes in cursive script, likely a signature or title, located at the top left of the page.



© 2021 Lloyd's Register Foundation