

ANNUAL SURVEYS.

43212

SATURDAY 1 DEC 1883

No. 10022 Survey held at London Date, first Survey Nov 22 Last Survey Nov 22 1883
 No. in Reg. Book. on the Barge "PLOTTER" Master Day (No. of Visits)
451 Net 414 Built at Sunderland When built 1858 Year. Month.
 Tonnage Gross 414 Under Dk. 396 By whom built Thompson & Co Owners Scrutton & Sons
 Port belonging to London Destined Voyage St. Kitts, West India
 If Surveyed Afloat or in Dry Dock Union Dry Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

✓ Last Survey, No. 8279 Port of Grp. Cly Years assigned 15 Character in Register Book. A.1
 Present Condition of the Decks Half Sun Lou 76
 Waterways } Treenails }
 Comings } Breasthooks and Stemson }
 Upper Deck Beams & Fastenings } Transoms, Pointers, and Crutches }
 Lower Deck Beams & Fastenings } Timbers of the Frame at the Openings }
 Planksheers } Ditto ditto at other places }
 Sheerstrakes } Keelsons }
 Topsides } Clamps and Shelves }
 Wales } Ceiling }
 Plank (Bottom) and Counter } Rudder }
 Engine Room Skylights } Coal Bunkers, Openings, Lids, &c. } Scuppers } Cargo and Main Hatchways } Hatches }
 General Observations, Opinion as to Class, &c. This vessel was placed in dry dock to sight the bottom, owners survey for sale, no transfer however was effected wrote to Messrs Scrutton advising them that present class would shortly expire, see letter attached. The overlooker verbally informed me that the owners intended to defer their consideration of the matter until the vessel returned from her present voyage.

Committee's Minute TUESDAY 4 DEC 1883
 Character assigned No action taken J. M. Edward John Tierney Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 10022 Survey held at London Date, first Survey Nov 22 Last Survey Nov 22 1883
 No. in Reg. Book. on the Barge GEORGETOWN Master not known (No. of Visits)
209 Net 414 Built at Sunderland When built 1858 Year. Month.
 Tonnage Gross 414 Under Dk. 391 By whom built Scrutton & Sons Owners
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Union Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42633 Port of Low Years assigned 13 Character in Register Book. A.1
 Present Condition of the Decks 33 Lou 79. 47 years in red
 Waterways } Treenails }
 Comings } Breasthooks and Stemson }
 Upper Deck Beams & Fastenings } Transoms, Pointers, and Crutches }
 Lower Deck Beams & Fastenings } Timbers of the Frame at the Openings }
 Planksheers } Ditto ditto at other places }
 Sheerstrakes } Keelsons }
 Topsides } Clamps and Shelves }
 Wales } Ceiling }
 Plank (Bottom) and Counter } Rudder }
 Engine Room Skylights } Coal Bunkers, Openings, Lids, &c. } Scuppers } Cargo and Main Hatchways } Hatches }
 General Observations, Opinion as to Class, &c. This vessel was placed in dry dock to sight bottom for change of owners, purchasers name did not transpire. Wrote to Messrs Scrutton acquainting them that her present class would shortly expire. See copy of letter attached.

Committee's Minute TUESDAY 4 DEC 1883
 Character assigned No action taken J. M. Edward John Tierney Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)