

## ANNUAL SURVEYS.

43227  
FRIDAY 30 NOV 1893

No. 87 Survey held at Louisa Date, first Survey Nov 23 Last Survey Nov 24 1888  
No. in Reg. Book. on the Iron Screw Steamer SAINT MARK Master Johnson  
Tonnage 1098 Built at Stockton When built 1878  
Gross 1708 By whom built Richardson, Duck Owners H Briggs & Sons  
Under Dk. 559 Port belonging to Louisa Destined Voyage Port Said via Cardiff  
If Surveyed Afloat or in Dry Dock Regent Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5330 Port of Hull Classed 100 A.1.

Present Condition of the

Decks goodWaterways 4Comings 4Upper Deck Beams & Fastenings 4Lower Deck Beams & Fastenings 4Planksheers 4Sheerstrakes 4Topsides 4Wales 4Plank (Bottom) and Counter 4Treenails Quint where seen GoodBreasthooks and Stems 4Transoms, Pointers, and Crutches 4Timbers of the Frame at the Openings 4Ditto ditto at other places 4Keelsons 4Clamps and Shelves 4Ceiling 4Rudder 4Copper or Y.M. 4When put on 4Caulking of 4Bottom, Deck, & Waterways 4Windlass and Capstan GoodPumps 4Boats 5Masts, Yards, &c. 4Condition, how ascertained from deckSails 1 SuitAnchors, No. of 3 B-18-2 KCables what seenHawsers and Warps SufficientStanding and Running Rigging goodEngine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches 4

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, the bottom examined scraped & painted she now appears eligible to remain as classed being in a sound and efficient condition

Committee's Minute

Character assigned

TUESDAY 11 DEC 1893

Surveyor to Lloyd's Register of British and Foreign Shipping

Certificate (if required, to be sent as per margin) Paid 18

No. 87 Survey held at Louisa Date, first Survey Nov 23 Last Survey Nov 24 1888

No. in Reg. Book. on the Iron Screw Steamer SAINT MARK Master Johnson

Tonnage 1098 Built at Stockton When built 1878  
Gross 1708 By whom built Richardson, Duck Owners H Briggs & Sons  
Under Dk. 559 Port belonging to Louisa Destined Voyage Port Said via Cardiff

If Surveyed Afloat or in Dry Dock Regent Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5330 Port of Hull Classed 100 A.1.

Present Condition of the

Decks goodWaterways 4Comings 4Upper Deck Beams & Fastenings 4Lower Deck Beams & Fastenings 4Planksheers 4Sheerstrakes 4Topsides 4Wales 4Plank (Bottom) and Counter 4Treenails Quint where seen GoodBreasthooks and Stems 4Transoms, Pointers, and Crutches 4Timbers of the Frame at the Openings 4Ditto ditto at other places 4Keelsons 4Clamps and Shelves 4Ceiling 4Rudder 4Copper or Y.M. 4When put on 4Caulking of 4Bottom, Deck, & Waterways 4Windlass and Capstan GoodPumps 4Boats 5Masts, Yards, &c. 4Condition, how ascertained from deckSails 1 SuitAnchors, No. of 3 B-18-2 KCables what seenHawsers and Warps SufficientStanding and Running Rigging goodEngine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches 4General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, the bottom examined scraped & painted she now appears eligible to remain as classed being in a sound and efficient condition

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping

Certificate (if required, to be sent as per margin) Paid 18