

43237

# Report of Survey for Repairs of Engines and Boilers.

(Received at London Office) THURSDAY 22 NOV 1883

No. \_\_\_\_\_  
No. in Reg. Book. Survey held at London Date, first Survey 12 Nov Last Survey 12 Nov 1883  
184 on the Machinery of the S. S. "Kent" (Number of Visits 1)

Tonnage, Gross	<u>2484</u>	Built at	<u>Glasgow</u>	When built	Year <u>1883</u>
Ditto, Net	<u>1620</u>	Owners	<u>M. Wigram &amp; Sons</u>	Port belonging to	<u>Glasgow</u>
Diameter of Cylinder	<u>38</u> <u>58</u>	Engines made by	<u>London &amp; Glasgow Co</u>	When made	Year <u>1883</u>
Length of Stroke	<u>48</u>	Boilers made by		When made	Year <u>1883</u>
Pressure of Steam	<u>80</u>	If Surveyed Afloat or in Dry Dock	<u>West India Dry Dock</u>	Classed	Years assigned. <u>100A1</u> <u>4-83</u>
Registered Horse Power	<u>300</u>	(State name of Dock.)			Character in Register Book. <u>100A1</u> <u>4-83</u>
Last Survey No.		Port			<u>+ L. M. C. 4.83.</u>

Particulars of Repairs and Examination Damage to Propeller  
(State cause of Repairs.)  
Examined Seacocks & connections.  
Two new propeller blades have been fitted & brass patches to the backs of all the blades. The blow off cocks have been overhauled & are now in a good condition.

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to remain as classed.

*It is submitted that this vessel is eligible to remain as classed*  
*M 21/11/83*

Entry or Registering Fee... £ : :  
(per Section 27.)  
Survey Fee (per Section 28) ... £ : : received by me,  
Certificate (if required) ... £ : : 188  
to be sent as per margin.  
(Travelling Expenses, if any, £ )

*C. W. Strömeyer*  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

FRIDAY 14 DEC 1883 188

Committee's Minute  
Assigned



(State if Report is also sent on the Hull of the Ship...)  
 (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute).  
 [Form No. 9-3000, 20/5/82.]

Insert Character precisely as in the Register Book.

040-040