

# ANNUAL SURVEYS.

43248

TUESDAY 11 DEC 1893

No.          Survey held at London Date, first Survey 27<sup>th</sup> Nov Last Survey 4<sup>th</sup> Dec 1893  
 No. in Reg. Book. on the Barque "Panda" Master W. Burgess  
 Tonnage { Net 324 Built at Denmark When built 1874 Month. 10<sup>th</sup>  
 { Gross 341 By whom built Vang Owners Bullard, King & Co  
 { Under Dk. 307 Port belonging to London Destined Voyage West Indies.  
 If Surveyed Afloat or in Dry Dock In Horseferry Dry Dock Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)

Last Survey, No. 42195 Port of London Classed 12 Years assigned. 12 Character in Register Book. A.1  
 Present Condition of the Decks good Treenails good H.T. Lon. & 1 2, & 3.  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan good  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats do  
 Planksheers do Keelsons do Masts, Yards, &c. do  
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from the deck  
 Topsides do Ceiling do Sails good  
 Wales do Rudder do Anchors, No. of 3 B. 1 S. 2 K.  
 Plank (Bottom) and Counter do Copper or Y.M. good When put on 6/81 Cables complete  
 Caulking of Bottom, Deck, & Waterways good Hawsers and Warps good  
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers good Cargo and Main Hatchways good Hatches good.

General Observations, Opinion as to Class, &c. The bottom has been sighted and the yellow metal sheathing repaired. The raised quarter deck recaulked. Vessel surveyed with part outward cargo in the hold. She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute J.H. Truscott FRIDAY 14 DEC 1893  
 Character assigned 12 A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.          Survey held at          Date, first Survey          Last Survey          18      
 No. in Reg. Book. on the          Master          (No. of Visits         )  
 Tonnage { Net          Built at          When built          Year.          Month.           
 { Gross          By whom built          Owners           
 { Under Dk.          Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock          Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)

Last Survey, No.          Port of          Classed          Years assigned.          Character in Register Book.           
 Present Condition of the Decks          Treenails           
 Waterways          Breasthooks and Stemson          Windlass and Capstan           
 Comings          Transoms, Pointers, and Crutches          Pumps           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings          Boats           
 Lower Deck Beams & Fastenings          Ditto ditto at other places          Masts, Yards, &c.           
 Planksheers          Keelsons          Condition, how ascertained           
 Sheerstrakes          Clamps and Shelves          Sails           
 Topsides          Ceiling          Anchors, No. of           
 Wales          Rudder          Cables           
 Plank (Bottom) and Counter          Copper or Y.M.          When put on          Hawsers and Warps           
 Caulking of Bottom, Deck, & Waterways          Standing and Running Rigging           
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches         

General Observations, Opinion as to Class, &c.           
 Committee's Minute           
 Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83. (If a Steam Ship, state if a Report is also sent on the Machinery. The Surveyors are requested not to write on or below the space for Committee's Minute.) (Insert Character precisely as in Register Book.)

LOND 71-0452

