

Report of Survey for Repairs of Engines and Boilers.

No. 493 (Received at London Office, **FRIDAY 18 JAN 1884**)
 No. in Reg. Book. 493 Survey held at London Date, first Survey 12 June 83 Last Survey 14th Dec^r 1883
 on the Machinery of the "Dunrobin Castle" (Number of Visits 3)
 Tonnage, Gross 2811 Built at Glasgow When built 1875
 Ditto, Net 1784 Owners D. Currie & Co Port belonging to London
 Diameter of Cylinder 47 & 75 Engines made by R. Napier & Sons When made 1875
 Length of Stroke 48 Boilers made by Do. When made 1875
 Pressure of Steam 60 lbs. If Surveyed Afloat or in Dry Dock (State name of Dock.)
 Registered Horse Power 300 Classed 100 A 1
 Last Survey No. 12.82 Port London Lm & 4.80

Particulars of Repairs and Examination Special Survey No. 2.

(State cause of Repairs.)

Examined the cylinders, valves, pumps and crank shafts
 found them in good condition
 Boilers & safety valves examined and found good
 Sea cocks & propeller fastenings examined found
 Satisfactory
 Safety valves set to blow at 60 lbs.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is now in good order and safe working condition and eligible in my opinion to have the notification Lm & 12.83 recorded subject to the resurvey of boilers in 12 months as per Rule

Entry or Registering Fee... £ - : - :
 (per Section 27.)
 Survey Fee (per Section 28) ... £ 3 : 3 : 0
 Certificate (if required) ... £ 5 : 5 : 0
 to be sent as per margin.
 (Travelling Expenses, if any, £)

received by me,

28 Jan 1884

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 22 JAN 1884 188

Assigned

Lm & 12.83



Lloyd's Register
Foundation