

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office **FRIDAY 18 JAN 1884**)
 No. in Reg. Book. Survey held at London Date, first Survey 13 Dec. Last Survey 28 Dec 1883
135 on the Machinery of the S. S. "Carrilla" (Number of Visits 8)

Tonnage, Gross	<u>722</u>	Built at	<u>Newcastle</u>	When built	<u>1866</u>
Ditto, Net	<u>956</u>	Owners	<u>London S S Co</u>	Port belonging to	<u>London</u>
Diameter of Cylinder	<u>26 57</u>	Engines <u>Comp</u> by	<u>McC & Co Eng Wks</u>	When made	<u>1874</u>
Length of Stroke	<u>30</u>	Boilers made by		When made	<u>1874</u>
Pressure of Steam	<u>75</u>	If Surveyed Afloat or in Dry Dock	<u>Pontoons</u>	Classed	<u>100H1</u>
Registered Horse Power	<u>160</u>	(State name of Dock.)		Years assigned.	<u>12 82</u>
Last Survey No.		Port		Character in Register Book.	<u>LME279. 135. 3.85</u>

Particulars of Repairs and Examination Damage & Special Survey
 (State cause of Repairs.)

Examined Leacocks and connections & found them good. The stern bush & liner of tailshaft had worn down. A new lignum vitae bush and has been fitted and the tailshaft liners turned true and the propeller refitted.

Examined Crankshaft and thrust shaft & found them good.

Examined Pumps, cylinders, slide valves and condenser & found them good.

Examined boilers & found them good.

Several of the bilge pipes have had to be repaired & renewed.


General Observations, Opinion, and Recommendation:— The machinery of this vessel appears now to be in a safe working condition and is in my opinion eligible to have the notification L. M. C. 1. 84 recorded in the Register Book.

Damage £ 3.3
 Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ 2.2 } — received by me, £ 7.8
 Certificate (if required) ... £ : : } 22/1 1884
 to be sent as per margin.
 (Travelling Expenses, if any, £)

C. D. Spromeyer
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUESDAY 22 JAN 1884 188

Assigned L. M. C. 1. 84



Form No. 9-3000, 20/7/82. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in the Register Book.

It is submitted that this vessel is eligible to have the notification Am 6 11.83 recorded subject to the mesurment of boilers as per Rule

20.9
15/11/84

[Faint, mostly illegible handwritten text in cursive script, likely bleed-through from the reverse side of the page.]



© 2021
Lloyd's Register
Foundation

Boiler of Engines for Boilers to provide for the