

43392
REPORT of SURVEY for REPAIRS, &c.

Received at London Office
TUESDAY 22 JAN 1884

No. in Survey held at *London* Date, first Survey *Dec 20/83* Last Survey *January 9th 1884*
Reg. Book: *330* on the *Composite Ship John R. Worcester* Master
Official Number *54596*
TONNAGE under Tonnage Deck *781*
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage *844*
Crew Space, as per Rule
Register Tonnage, cut on Beam *844*
Engine Room
Reg. Tons as St' mer, cut on Bm.
Built at *Port Glasgow* When built *1865* - *12*
Owners *J. Patton Junr & Co* Port belonging to *London*
Residence
By whom built *Patterson* Destined Voyage
If Surveyed Afloat or in Dry Dock *Poplar Dry Dock & Afloat*
(State Name of Dock)
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Classed *18 A 1*
H. J. Lgn *72*
S. S. Lgn *78*
Society's Freeboard (if assigned) as painted on Ship
MOULDED DEPTH of Ship, if not yet recorded in Register Book

Last Survey, No. *39114* Port *Low*
REPAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.
State dates of any letters respecting this case

This vessel is now for sale, has been placed in Dry Dock for sighting the bottom. - The Metal is much worn off - it is in a bad state, and requires to be stripped, and the after Keel appears to have dropped from the Sternpost leaving the joint very much open, and it requires to be set up and refastened.

The Owners have been advised in reference to the above and of Survey for Continuation being due.

Present Condition of the
Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the openings
Ditto Ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper (or Y.M.) *on felt* When put on *4, 1880*
(State if on Felt.)
Cement (if Iron Ship)
Caulking of Bottom, Deck, & Waterways
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging
Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches —

General Observations, Opinion as to Class, &c. *This vessel appears to be now due for Survey for Continuation, and until she has been prepared for Survey and examined, and the necessary repairs effected, no recommendation can be made for classification.*

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 188 }
Certificate (if required) } £ : :
to be sent as per margin... }

(Travelling Expenses, if any, £)
Committee's Minute
Character assigned *Expiated*

J. W. Miles.
Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 25 JAN 1884

© 2021
Lloyd's Register
Foundation