

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, **TUESDAY 5 FEB 1884**)
No. in Reg. Book. Survey held at London Date, first Survey _____ and Last Survey Jan. 31st 1884

221 on the Machinery of the S. S. "Pelaw" (Number of Visits 1)

Tonnage, Gross <u>793</u>	Built at <u>Sunderland</u>	When built <u>1869</u>
Ditto, Net <u>593</u>	Owners <u>Comm. S. S. Co.</u>	Port belonging to <u>London</u>
Diameter of Cylinder <u>38"</u>	Engines made by <u>N. E. Marine Co.</u>	When made <u>1869</u>
Length of Stroke <u>30"</u>	Boilers made by _____	When made <u>1879</u>
Pressure of Steam <u>45 lb.</u>	If Surveyed Afloat or in Dry Dock <u>Bridge D. Dk.</u>	Classed <u>95A1</u>
Registered Horse Power <u>90</u>	(State name of Dock.)	Years assigned. _____
Last Survey No. _____	Port _____	Character in Register Book. _____

Particulars of Repairs and Examination In Annual Survey
(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller & its connections sound & the stern bush worn down $\frac{1}{4}$ ". Boilers examined fire stays in Combustion Chamber back of Port wing furnace & the remainder of boiler found in good condition.

General Observations, Opinion, and Recommendation:— The boiler being now in good & safe working condition the machinery as far as seen, renders the vessel eligible in my opinion to remain as classed & have the certification B. S. 1. 84 recorded provided that the boiler is again examined within 12 months as per rule.

Entry or Registering Fee... £ — : —	received by me, <u>Geo. E. Thompson</u>
Survey Fee (per Section 28) ... £ 1 : 1	
Certificate (if required) ... £ " : " 20 th Feb 1884	
(Travelling Expenses, if any, £ _____)	
Committee's Minute _____	Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.
Assigned <u>B-S 1, 84</u>	

FRIDAY 8 FEB 1884 188



It is submitted that this vessel
is eligible to have the notification
B S 184 recorded Subject
to the resurvey of boilers as
per Rule

W F
21/2/84



© 2021

Lloyd's Register
Foundation