

Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office) **TUESDAY 12 FEB 1884**  
No. in Survey held at London Date, first Survey 1 Jan'y Last Survey 1 Jan'y 1884  
Reg. Book. 448 on the Machinery of the S. S. Trevethick (Number of Visits 5)  
Tonnage, Gross 779 Built at Newcastle When built 1866  
Ditto, Net 489 Owners J. Fenwick & Co Port belonging to Newcastle  
Diameter of Cylinder 26 57 Engines made by Vic & Co E. Wks Co When made 1873  
Length of Stroke 30 Boilers made by \_\_\_\_\_ When made 1873  
Pressure of Steam 71 If Surveyed Afloat or in Dry Dock Tidal Basin & Docks Years assigned 1 Character in Register Book A 1  
Registered Horse Power 99 (State name of Dock.) Docks 9.82  
Last Survey No. \_\_\_\_\_ Port BS. 9.82

Particulars of Repairs and Examination Damage & Boiler Survey  
(State cause of Repairs.)  
Examined Seacocks & connections & found them good.  
Examined the two main boilers & superheater & found them good.  
Examined high pressure & low pressure cylinders & slide valves & pumps found them good.  
Examined crankshaft and found a circumferential crack in aft fillet of forward crankshaft. A new crankshaft has been fitted.

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to have the notification BTM 8.1.84.

Damage 2 2 -  
Entry or Registering Fee... £ - : - :  
Survey Fee (per Section 28) 4/184 £ 1 : 1 : received by me, 16/2 1884  
Certificate (if required) ... £ : : 7.7.8  
(Travelling Expenses, if any, £ )

C. R. Brown  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 15 FEB 1884 188

Assigned BTM 8, 1, 84



Lloyd's Register  
Foundation

It is submitted that this vessel  
is stable she slopes as recommended  
B & MS 1/84, subject to the boilers being  
again surveyed within 12 mos  
from date of survey on

account of age and  
condition (See previous  
Report limiting boilers).

M  
11.2.84



© 2021

Lloyd's Register  
Foundation

Report of Survey for Repairs of Engines and Boilers