

43476

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, TUESDAY 12 FEB 1884)

No. in Reg. Book. *161* Survey held at *London* Date, first Survey *14 Jan'y* Last Survey *—* 188*4*
on the Machinery of the *S. S. Trevotdale* (Number of Visits *1*)
Tonnage, Gross *1580* Built at *Greenock* When built *1882*
Ditto, Net *1018* Owners *R. Mackill & Co* Port belonging to *Glasgow*
Diameter of Cylinder *32.60* Engines made by *R. Stul & Co* When made *1882*
Length of Stroke *42* Boilers made by *—* When made *1882*
Pressure of Steam *80* If Surveyed Afloat or in Dry Dock *Pontoons* (State name of Dock.)
Registered Horse Power *165* Classed *100 A1*
Last Survey No. *—* Port *—* *5.83*
+ L.M.C. 7.82

Particulars of Repairs and Examination *Removal of Stern Post*
(State cause of Repairs.)
Examined Sea cocks & connections & Stern tube & shaft & found them good.
The Stern tube & shaft have been replaced.

General Observations, Opinion, and Recommendation:— *As far as seen the machinery of this vessel is now in a safe working condition and is in my opinion eligible to remain as classed.*

Entry or Registering Fee... £ : :
(per Section 27.)
Survey Fee (per Section 28) ... £ — : — received by me,
Certificate (if required) ... £ : : 188
to be sent as per margin.
(Travelling Expenses, if any, £)

Committee's Minute

Assigned

FRIDAY 16 FEB 1884 188

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON672-0117

(State of Repairs and Examination, to be clearly stated.)

Insert Character precisely as in the Register Book.