

Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office) TUESDAY 12 FEB 1884

No. in Reg. Book. Survey held at *London.*

Date, first Survey *+*

Last Survey *Jan: 14th* 1884

427 on the Machinery of the *S. S. "Linden"*

(Number of Visits *1*)

Tonnage, Gross *1068*

Built at *Sunderland*

When built *1877*

Ditto, Net *987*

Owners *R. Thorman & Co.*

Port belonging to *London*

Diameter of Cylinder *27" + 50"*

Engines made by *S. Clarke*

When made *1877*

Length of Stroke *36*

Boilers made by *Do.*

When made *1877*

Pressure of Steam *70 lbs.*

If Surveyed Afloat or in Dry Dock *Union S. Dock.*
(State name of Dock.)

Years assigned. Character in Register Book.

Registered Horse Power *99*

Classed *100A1*

Last Survey No.

Port

L.M.C. 4-81 B.S. 7-83.

Particulars of Repairs and Examination *For Annual Survey.*
(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller & its connections sound & tail shaft down $\frac{1}{4}$ ". No damage to engines.

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed.*

Entry or Registering Fee... £ : :

Survey Fee (per Section 28) ... £ — : — :

Certificate (if required) ... £ : :
to be sent as per margin.

received by me,
188

(Travelling Expenses, if any, £)

Committee's Minute

FRIDAY 15 188

Assigned

Geo. E. Wilkinson.
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LON 672 0119