

# ANNUAL SURVEYS.

43578

(Received at London Office) SATURDAY 15 MARCH 1884

No. \_\_\_\_\_ Survey held at London Date, first Survey 27 Feb Last Survey 12 March 1884  
 No. in Reg. Book. on the Ship "Holmsdale" Master D. R. Bolt.  
 Tonnage { Net 1250 Built at Sunderland. When built 1858  
 { Gross 1352  
 { Under Dk. 1102 By whom built J. M. Reed Owners Anderson, Anderson & Co  
 Port belonging to Aberdeen Destined Voyage Adelaide.  
 If Surveyed Afloat or in Dry Dock in West India Dry Dock Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)

Last Survey, No. 42357 Port of Lon. Classed 15 A. 1.  
 Present Condition of the Decks good MEASURED DEPTH of Ship, if not yet recorded in Register Book  
 Waterways do Treenails good Covk. Lon. 73-14  
 Comings do Breasthooks and Stenson do H.I. Lon. 79.  
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do Windlass and Capstan good  
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do  
 Planksheers do Ditto ditto at other places not seen Boats do  
 Sheerstrakes do Keelsons good Masts, Yards, &c. do  
 Topsides do Clamps and Shelves do Condition, how ascertained from the deck  
 Wales do Ceiling do Sails good  
 Plank (Bottom) and Counter do Rudder do Anchors, No. of 3 B. 1 S. 2 K  
 Engine Room Skylights do Copper or Y.M. good When put on 3, 4, 3 Cables good  
 Coal Bunkers, Openings, Lids, &c. do Caulking of Bottom, Deck, & Waterways good Hawsers and Warps do  
 Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. The bottom has been sighted & the yellow metal sheathing found in good condition. Fore lower rigging renewed. Fore topgallant mast renewed.  
This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 13 MARCH 1884  
 Character assigned J. H. Truscott.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18


No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 { Gross \_\_\_\_\_  
 { Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ MEASURED DEPTH of Ship, if not yet recorded in Register Book  
 Waterways \_\_\_\_\_ Treenails \_\_\_\_\_  
 Comings \_\_\_\_\_ Breasthooks and Stenson \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Topsides \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Wales \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Rudder \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Copper or Y.M. When put on \_\_\_\_\_  
 Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_  
 Hatches \_\_\_\_\_

General Observations, Opinion as to Class, &c. \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/88. (If a Steam Ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Insert Character precisely as in Register Book.)

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/88. (If a Steam Ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Insert Character precisely as in Register Book.)



6220-27970