

ANNUAL SURVEYS.

43643

No. Survey held at London Date, first Survey 19th March Last Survey 26th March 1884
No. in Reg. Book. on the Iron Ssw. "Carib" Master H. Vicary.
232 912 Built at Stockton When built 1882 9th
Tonnage Gross 1437 Under Dk. 1088 By whom built Richardson, Duck & Co Owners Anderson, Anderson & Co
Port belonging to Stockton Destined Voyage Jamaica.
If Surveyed Afloat or in Dry Dock In West India Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 43028 Port of Lon Classed 100 A.1 9583.
Present Condition of the Decks good BREULDED DEPTH of Ship, if not yet recorded in Register Book good
Waterways D^o Breasthooks and Stemson D^o
Comings D^o Transoms, Pointers, and Crutches D^o
Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
Planksheers D^o Keelsons D^o
Sheerstrakes D^o Clamps and Shelves
Topsides D^o Ceiling D^o
Wales D^o Rudder D^o
Plank (Bottom) and Counter D^o Copper or Y.M. When put on
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. The bottom has been examined and coated.
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 1 APRIL 1884
Character assigned J. H. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Net Built at When built
Gross By whom built Owners
Under Dk.
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed
Present Condition of the Decks BREULDED DEPTH of Ship, if not yet recorded in Register Book
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



(If a Steam Ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)

(Insert Character precisely as in Register Book.) (Insert Character precisely as in Register Book.)

LON672-0305