

Report of Survey for Repairs of Engines and Boilers.

43669

No. _____ (Received at London Office, _____)

No. in Reg. Book. *Survey held at London* Date, first Survey *28th Feb.* Last Survey *5 March 1884*

971 on the Machinery of the *S. S. "Statira"* (Number of Visits *2*)

Tonnage, Gross *994* Built at *Newcastle* When built *1868*

Ditto, Net *733* Owners *London Steam S Co* Port belonging to *London*

Diameter of Cylinder *26* *57* Engines *Made by Vic Dock E. Co.* When made *1875*

Length of Stroke *30* Boilers made by _____ When made *1875*

Pressure of Steam *75* If Surveyed Afloat or in Dry Dock *Victoria Dock* (State name of Dock.)

Registered Horse Power *160* Classed *100 A1* Years assigned *2.83.* Character in Register Book *MS. 3.84. BS. 5.83.*

Last Survey No. _____ Port _____

Particulars of Repairs and Examination

Boiler Survey

Examined Superheater and two main boilers and found them in a good condition

Examined the safety valves (adjusted) and found them in a good condition

General Observations, Opinion, and Recommendation:— *As far as seen the machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 3-83 recorded in the Register Book.*

Entry or Registering Fee... £ - - -

Survey Fee (per Section 28) *10/4 84* £ *2:2*

Certificate (if required) ... £ : : *received by me, 16/4 1884*

(Travelling Expenses, if any, £ _____)

Committee's Minute

THURSDAY 10 APRIL 1884


188

Assigned

B.S. 3-84

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

C. J. Bromeyer



Lloyd's Register Foundation

LON672-0336

It is submitted that this vessel is
eligible to have the notification
P.S. 384 recorded Subject to the
resurvey of boilers as per rule

D.E

17/3/84



© 2021

Lloyd's Register
Foundation