

ANNUAL SURVEYS.

43813
MONDAY 23 MAY 1884

(Received at London Office,)

No. Survey held at London Date, first Survey 21/5/84 Last Survey 22/5/84 1884
 No. in Reg. Book. on the Composite Barque "Maiko" Master Boutaniche
 Tonnage 516 Built at Sunderland When built 1869-4
536 Gross Under Dk. 497 By whom built W. & Co Owners Huluck Martin & Co
 Port belonging to London Destined Voyage Hongkong
 If Surveyed Afloat or in Dry Dock Green Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)


Last Survey, No. 28742 Port of Sir. Sir Classed 18-A-1
 Present Condition of the Decks Good Treenails Good
 Waterways 4 Breasthooks and Stemson 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shelves 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Gal When put on 683
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. This vessel placed in dry dock to sight bottom she now appears to be in a sound and efficient condition eligible to remain as classed.

Committee's Minute TUESDAY 27 MAY 1884
 Character assigned 18A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LON672-0499

(If a Steam Ship, state if a Report is also sent on the Machinery)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/9/83.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)