

# REPORT of SURVEY for REPAIRS, &c.

(Received at London Office,

43837  
SATURDAY 24 MAY 1884

No. in Survey held at London Date, First Survey 24<sup>th</sup> April Last Survey 25<sup>th</sup> April 1884  
Reg. Book. 33A on the Steel Sloop "Lydian Monarch" (Shelter Sk.) Master \_\_\_\_\_  
TONNAGE under Tonnage Deck 2855 Built at Dumbarton When built 1881 YEAR. MONTH.  
Ditto of Spar Deck, or Awning Deck \_\_\_\_\_ Owners Royal Exchange Ship Co (Lim.) Port belonging to London.  
Ditto of Poop \_\_\_\_\_ Residence \_\_\_\_\_  
Ditto of Raised Qr. Dk. \_\_\_\_\_ By whom built A. McMillan & L. Destined Voyage \_\_\_\_\_  
Ditto of Houses on Deck \_\_\_\_\_ If Surveyed Afloat or in Dry Dock Afloat in Millwall Docks.  
Ditto of Forecastle \_\_\_\_\_ (State Name of Dock) \_\_\_\_\_  
Gross Tonnage 3916 Reg. Tons as St<sup>r</sup>mer, cut on Bm. 2546

Length of Poop \_\_\_\_\_ ft. Ditto, Forecastle \_\_\_\_\_ ft. Ditto, Raised Qr. Deck \_\_\_\_\_ ft.  
Last Survey, No. 43185 Port Son load line 23 ft 6 in Classified 100 A.1.  
REPAIRS, OR EXAMINATION AS PER RULE

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage to be separate from Repairs from other causes.) Society's Freeboard (if assigned) as painted on Ship { in salt water \_\_\_\_\_ in fresh water \_\_\_\_\_

State dates of any letters respecting this case \_\_\_\_\_ MOULDED DEPTH of Ship, if not yet recorded in Register Book \_\_\_\_\_

right  
A house on deck aft has been erected - length 54 ft, breadth 22 ft, height 7 1/2 ft.  
- frames 2 1/2" x 2 1/2" x 5/16" with brackets at heels - beams 3" x 3" x 5/16" - spaced 3 ft apart - side  
plating 5/16" - deck on top of house 2 1/2" thick - two pillars to each beam - see sketch attached.  
This house having been erected on the shelter deck without the sanction of the Committee  
a letter (copy attached) was written to the Owners, informing them that such erections  
not being acknowledged by the Rules cannot without the Committee's permission be  
admitted & that the work and construction are in our opinion very objectionable  
& cannot be favorably reported on. This house was nearly completed before we  
were aware that it was being constructed and the work & construction have not been  
remedied.

## Present Condition of the

Decks <u>good</u>	<del>Trunnels or Rivets</del> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, <del>Pointers</del> , and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	<del>Timbers of the Frame</del> at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	<del>Ditto</del> <u>Ditto</u> at other places <u>do</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Sails <u>good</u>
Sheerstrakes <u>do</u>	<del>Clamps and Shells</del> <u>do</u>	Anchors No. of <u>complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Cables <u>good</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
<del>Plank (Bottom) and Counter</del> <u>do</u>	<del>Copper (on R.M.)</del> When put on <u>do</u>	Standing & Running Rigging <u>do</u>
	(State if on Tolls) <u>do</u>	
	Cement (if Iron Ship) <u>do</u>	
	Caulking of Bottom, Deck, & Waterways <u>do</u>	

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
General Observations, Opinion as to Class, &c. This vessel is in good and efficient condition except as  
regards the house on shelter deck above alluded to which if sanctioned by the Committee  
requires in our opinion to have the work & construction improved, which are light  
& flimsy.

Entry or Registration Fee ... £ : :  
(per Section 27, Scale I. or II.)  
Survey Fee (per Section 28) ... £ : :  
Special Damage Fee (per Section 28) £ : :  
\* Certificate (if required) ... £ : :  
Travelling Expenses (if any) ... £ : :  
Second Surveyor's Fee (if any) ... £ : :  
received by me, }  
188 }

Committee's Minute

Character assigned

TUESDAY 5 JUNE 1884

THURSDAY 5 JUNE 1884

Surveyor to Lloyd's Register of British and Foreign Shipping.

J. H. Truscott.

W. L. Davey



Gr: Once 5<sup>th</sup> June, 1884  
Approve Surveyors  
Remarks - write  
Owners

Oct 6. 6. 84  
G.M.



© 2021

Lloyd's Register  
Foundation