

Report of Survey for Repairs of Engines and Boilers.

43919

No. _____ (Received at London Office) **TUESDAY 17 JUNE 1884**

No. in Reg. Book. *312* Survey held at *London* Date, first Survey *28th April* Last Survey *1884*

on the Machinery of the *S. S. John McIntyre* (Number of Visits *1*)

Tonnage, Gross *991* Built at *Newcastle* When built *1863*

Ditto, Net *630* Owners *J. Fenwick & Son* Port belonging to *London*

Diameter of Cylinder *26* *57* Engines made by *McC & Co. & Wks.* When made *1865*

Length of Stroke *30* Boilers made by _____ When made *1875*

Pressure of Steam *75* If Surveyed Afloat or in Dry Dock *McC & Co.* Years assigned *90 A1*

Registered Horse Power *99* (State name of Dock.) _____ Classed *S.S. 3-80* *9.83.*

Last Survey No. *17088* Port *London* *L.M.C. 881 B8 883*

Particulars of Repairs and Examination

Boiler Survey

Examined the two main boilers and super-heater and them good. Three stays in superheater have been renewed and 3 patches fitted in the combustion chambers.

The safety valves. (lever & weights) were found to be in good working order.

Ex. the high & low pressure cylinders and slides & pumps & found them good.

The crankshaft is being replaced by a new one of steel.

General Observations, Opinion, and Recommendation:— *As far as seen the machinery is in a good working condition and in my opinion the vessel is eligible to have the notification B.S. 4.88 recorded in the Register Book*

Entry or Registering Fee... £ : :
(per Section 27.) *21/6*

Survey Fee (per Section 28) ... £ *1:1* : : — received by me, *W. H. ... 1884*

Certificate (if required) ... £ : :
to be sent as per margin.

(Travelling Expenses, if any, £)

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRIDAY 20 JUNE 1884 188

Assigned

B.S. 4.88

C. W. Stromeier

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

LON672-0624

[State if Report is also sent on the Hull of the Ship. (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)]

[Form No. 9-3000, 20/5/82.] (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in the Register Book.

It is submitted that this vessel is
eligible to have the notification
BS.4.84 recorded the boilers being
subject to resurvey as per Rule.

DS.

10/6/84



© 2021

Lloyd's Register
Foundation

Table of Survey for Repairs of Engines and Boilers