

Report of Survey for Repairs of Engines and Boilers.

43927

No. _____ (Received at London Office) **TUESDAY 17 JUNE 1884**
 No. in Reg. Book. Survey held at London Date, first Survey 30 April Last Survey 5 May 1884
5 on the Machinery of the S. S. Dacia (Number of Visits 3)
 Tonnage, Gross 1855 Built at Liverpool When built 1867
 Ditto, Net 1473 Owners India Rub. & Co. Port belonging to London
 Diameter of Cylinder 23, 23, 45, 45 Engines made by G. Clark When made 1867
 Length of Stroke 36 Boilers made by _____ When made 1875
 Pressure of Steam 70 If Surveyed Afloat or in Dry Dock Thames & W. Classed Years assigned 1 Character in Register Book 1. 83.
 Registered Horse Power 170 (State name of Dock.)
 Last Survey No. _____ Port 13 JMS. 6. 80

Particulars of Repairs and Examination

Part Special Survey Not.

Examined sea cocks and connections and found them good.

Examined the two main boilers and superheaters and found them in a good condition. Some of the furnace sides which are slightly pitted had been patched.

The safety valves were found in a good working condition.

Remained

General Observations, Opinion, and Recommendation:— As far as seen the machinery appears to be in a safe working condition and the vessel is in my opinion eligible to have the notification B.S. 5.84 recorded in the Register Book

Entry or Registering Fee... £ — : — : —
 Survey Fee (per Section 28) ... £ 2 : 2 : — received by me, 10 July 1884
 Certificate (if required) ... £ : 5 : 10 July 1884
 to be sent as per margin.
 (Travelling Expenses, if any, £ _____)

Committee's Minute

FRIDAY 20 JUNE 1884

Assigned

B. 8. 5, 84

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



LONG 72-0635

It is submitted that this vessel is
eligible to have the notification B.S.
5 84 recorded subject to the resurvey
of boilers in 12 months as per Rule

D.P.

16/6/84



© 2021

Lloyd's Register
Foundation