

Report of Survey for Repairs of Engines and Boilers.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey

19 May

Last Survey

26 May

1884

912

on the Machinery of the

S. S. Miranda

(Number of Visits

2

Tonnage, Gross

996

Built at

Newcastle

When built

1865

Ditto, Net

736

Owners

London Steam S Co.

Port belonging to

London

Diameter of Cylinder

25

48

Engines

Compound. Palmers

When made

1871

Length of Stroke

30

Boilers made by

When made

1871

Pressure of Steam

75

Registered Horse Power

140

If Surveyed Afloat or in Dry Dock

On Dock.

Classed

Years assigned.

80 A1

Last Survey No.

3374

Port

London

M.S. 2. 81.

BS 683.

Particulars of Repairs and Examination

Boiler Survey

(State cause of Repairs.)

Examined 2 main boilers and found them good a few patches in the combustion chambers have been repaired and the tubes renewed.

Examined the superheater and found it in a good condition.

The safety valves (loaded) were found in a good working condition

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 5.84 recorded in the Register Book

Entry or Registering Fee...

£ — : —

Survey Fee (per Section 28) ...

£ 2 : 2

Certificate (if required)

£ : :

to be sent as per margin.

(Travelling Expenses, if any, £)

received by me,

26/6 1884

7.4.6

C. E. Schromeyer

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 24 JUNE 1884

188

Assigned

B. S. 5.84



Lloyd's Register Foundation

LONG72-0663

It is submitted that this vessel
is eligible to have the notification
BS 5.84 recorded the boilers being
subject to resurvey as per Rule

W.P.

23/6/84



© 2021

Lloyd's Register
Foundation