

# ANNUAL SURVEYS.

43953

(Received at London, WEDNESDAY 13 JUNE 1884)

No. 5 Survey held at London Date, first Survey 16<sup>th</sup> June Last Survey 17<sup>th</sup> June 1884  
 No. in Reg. Book. on the Iron Screw "Oakdale" Master Gillings  
 Tonnage Net 897 Built at Hartlepool When built 1878 Year. 3<sup>rd</sup> Month.  
Gross 1408 By whom built E. Withy & Co Owners Steel, Young & Co  
Under Dk. 1094 Port belonging to London Destined Voyage Monte Video  
 If Surveyed Afloat or in Dry Dock In Rugg's Dry Dock. Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 571 Port of Gen. Classed 100 A.1  
 Present Condition of the Decks good MOULDED DEPTH of Ship, if not yet recorded in Register Book L.L. Lon. 1<sup>st</sup>-83. Character in Register Book. 11, 83  
 Waterways D<sup>o</sup> Breasthooks and Stemson D<sup>o</sup>  
 Comings D<sup>o</sup> Transoms, Pointers, and Crutches D<sup>o</sup>  
 Upper Deck Beams & Fastenings D<sup>o</sup> Timbers of the Frame at the Openings D<sup>o</sup>  
 Lower Deck Beams & Fastenings D<sup>o</sup> Ditto ditto at other places D<sup>o</sup>  
 Planksheers D<sup>o</sup> Keelsons D<sup>o</sup>  
 Sheerstrakes D<sup>o</sup> Clamps and Shelves D<sup>o</sup>  
 Topsides D<sup>o</sup> Ceiling D<sup>o</sup>  
 Wales D<sup>o</sup> Rudder D<sup>o</sup>  
 Plank (Bottom) and Counter D<sup>o</sup> Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways good  
 Windlass and Capstan good  
 Pumps D<sup>o</sup>  
 Boats D<sup>o</sup>  
 Masts, Yards, &c. D<sup>o</sup>  
 Condition, how ascertained from the deck  
 Sails good  
 Anchors, No. of 3 B. 1 S. 2 K  
 Cables good  
 Hawsers and Warps D<sup>o</sup>  
 Standing and Running Rigging D<sup>o</sup>  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. The bottom has been examined & coated. Rudder pintles rebushed. This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 21 JUNE 1884  
 Character assigned 100 A.1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.        Survey held at        Date, first Survey        Last Survey        18        
 No. in Reg. Book. on the        Master         
 Tonnage Net        Built at        When built        Year.        Month.  
Gross        By whom built        Owners         
Under Dk. Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock        Society's Freeboard (if assigned) as painted on Ship  
 Last Survey, No.        Port of        Classed         
 Present Condition of the Decks        MOULDED DEPTH of Ship, if not yet recorded in Register Book         
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways         
 Windlass and Capstan         
 Pumps         
 Boats         
 Masts, Yards, &c.         
 Condition, how ascertained         
 Sails         
 Anchors, No. of         
 Cables         
 Hawsers and Warps         
 Standing and Running Rigging         
 Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
 General Observations, Opinion as to Class, &c.       

Committee's Minute         
 Character assigned         
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

LON672-0667

(If a Steam Ship, state if a Report is also sent on the Machinery Min. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.) (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)