

ANNUAL SURVEYS.

44068
TUESDAY 22 JULY 1884

No. 3 Survey held at LONDON Date, first Survey July 9 Last Survey July 14 1884
 No. in Reg. Book. on the Iron Steamer Sabulamauzi Master Stuart
 Tonnage { Net 980 Built at Aberdeen When built 1882-5
 Gross 1537
 Under Dk. 998 By whom built Ball & Russell & Co Owners Fleming & Co
 Port belonging to Aberdeen Destined Voyage Natal
 If Surveyed Afloat or in Dry Dock Greenock Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 113663 Port of LONDON Classed 100A1
 Present Condition of the Decks Good Treenails Good
 Waterways 4 Breasthooks and Stemson 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shelves 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder re riveted
 Plank (Bottom) and Counter 4 Copper or Y.M. When put on
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Placed in dry dock the bottom cleaned & coated the rudder partly re riveted and the the bulwark on starboard side forward all loose rivets renewed. She now appears to be in a sound and efficient condition eligible in my opinion to remain as classed
 Committee's Minute August 5th 1884
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping. Edward J W Tierney
 Certificate (if required, to be sent as per margin) 8/8 Paid 5/- 1884

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____
 Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship
 Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18____

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/83. (If a Steam Ship, state if a Report is also sent on the Machinery. The Surveyors are requested not to write on or below the space for Committee's Minute.)

Lloyd's Register of British and Foreign Shipping. (Insert Character precisely as in Register Book.)

