

44074

11.8.84.

Survey, No. 43569 Port _____
IRS, OR EXAMINATION AS PER RULE _____

Society's Freeboard (if assigned) as painted on Ship

$\left\{ \begin{array}{l} \text{in salt water} \\ \text{in fresh water} \end{array} \right.$

MOULDED DEPTH of Ship, if not yet recorded in Register Book

This vessel placed in dry dock the bottom examined
cleaned & coated. Several rivets in Quadder and
a bolt apr renewed. &c. timbers cleared

Days	do
78	do
Deck Beams & Fastenings	do
Deck Beams & Fastenings	do
Decks	do
Drakes	do
Drum	do
(Bottom) and Counter	do

Breasthooks and Stemson

Transoms, Pointers, and Crutches.....

Timbers of the Frame at the openings

Ditto *Ditto* *at other places*

Keelsons

~~Clamps and Shelves~~ *Stinger*

Ceiling

Rudder

Copper (or Y.M.) — When put on
(State if on Felt.)

Cement (if Iron Ship)

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained *from dec*

Sails 2 Sails good
Anchors No. of 7 B, 1 S, 2 K

Cables *What seen* *Good*

Hawsers and Warps

Standing & Running Rigging

e Room Skylights *good* Coal Bunker, Openings, Lids, &c. *good* Scuppers *good* Cargo and Main Hatchways *good* Hatches *do*
al Observations, Opinion as to Class, &c. *2*

This Vessel appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

received by me,
188

Edward Geo Lister

Surveyor to Lloyd's Register of British and Foreign Shipping

Committee's Minute

Character assigned

TUESDAY 12 AUGUST 1884

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London

LON 673-0125

British King



© 2021

Lloyd's Register
Foundation