

444081

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,)

No. _____

No. in Reg. Book. 306 Survey held at London Date, first Survey 26 July Last Survey 30 1884

on the Machinery of the John Mc Lure (Number of Visits 2)

Tonnage, Gross 991 Built at Newcastle When built 1863

Ditto, Net 630 Owners J. Fenwick & Son Port belonging to London

Diameter of Cylinder 26 57 Engines made by Wick & Co Eng Wks When made 65

Length of Stroke 30 Boilers made by _____ When made 75

Pressure of Steam 75 If Surveyed Afloat or in Dry Dock Pontoons Classed 90 A 1

Registered Horse Power 99 (State name of Dock.)

Last Survey No. _____ Port _____ L.M.C. 8.81. 135.4.84.

Particulars of Repairs and Examination Completion of Special Survey
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Sea cocks & connections & found them good.
Examined HP Cylinder both crank pins and all liners of tail shaft & found them good.
The lignum vitae in stern tube has been renewed.

General Observations, Opinion, and Recommendation:— The machinery appears to be in a safe working condition and the vessel is in my opinion eligible to have the notification L.M.C. 4.84 recorded in the Register Book
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Survey Fee (per Section 28) <u>14/8/84</u> ...	£ 1 : 1	received by me, <u>[Signature]</u> <u>16 Aug 1884</u>
Special Damage Fee (per Section 28) ..	£ :	
*Certificate (if required)	£ :	
Travelling Expenses (if chargeable)	£ :	

It is submitted that this vessel is
eligible to have the notification
Ln 6 4.84 recorded, the boilers being
subject to resurvey as per Rule

D.F.

8/8/84



© 2021

Lloyd's Register
Foundation