

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office,

No.

No. in Survey held at

Date, First Survey

(No. of Visits

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Qr. Deck

ft.

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 43581 Port

REPAIRS, OR EXAMINATION AS PER RULE

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage to be separate from Repairs from other causes.)

Society's Freeboard (if assigned) as painted on Ship

in salt water

in fresh water

State dates of any letters respecting this case

MOULDED DEPTH of Ship, if not yet recorded in Register Book.

Annual Survey &c.

This vessel was placed in dry dock the bottom examined, scraped and painted. The timbers cleaned, & ceiling repaired where necessary.

It was contemplated to cut through the fore Boiler Room Bulkhead, to extend the Boiler space to the next watertight Bulkhead forward. (if Cross Bulkhead) to accommodate an additional boiler for working refrigerator. The idea for the present remains in abeyance till the vessel's return from her present voyage when it will be definitely decided.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Greenalls or Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper (or Y.M.)

(State if on Felt.)

Cement (if Iron Ship)

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Entry or Registration Fee ... £

Survey Fee (per Section 28) ... £

Special Damage Fee (per Section 28) £

* Certificate (if required) ... £

Travelling Expenses (if any) ... £

Second Surveyor's Fee (if any) ... £

received by me,

188

Committee's Minute

Character assigned

FRIDAY 15 AUGUST 1884

Surveyor to Lloyd's Register of British and Foreign Shipping.

NOT THE SURVEYORS ARE REQUESTED NOT TO WRITE ON THIS MAP

Dorunda



© 2021

Lloyd's Register
Foundation