

# Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

FRIDAY 29 AUGUST 1884

No. *166* in Reg. Book. Survey held at *London* on the Machinery of the *S. S. New Peldon* Date, first Survey *2 Aug* Last Survey *12 Aug 1884* (Number of Visits *3*)  
 Tonnage, Gross *821* Built at *Newcastle* When built *1865*  
 Ditto, Net *525* Owners *J. Fenwick & Son* Port belonging to *Newcastle*  
 Diameter of Cylinder *25 48* Engines made by *Palmer* When made *1878*  
 Length of Stroke *33* Boilers made by *Palmer* When made *1878*  
 Pressure of Steam *75* If Surveyed Afloat or in Dry Dock *Portoons* Classed *80 A1*  
 Registered Horse Power *99* (State name of Dock.)  
 Last Survey No. *7-83* Port *L.M.C. 5.81.*

## Particulars of Repairs and Examination

*Special Survey No 2*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

*Examined Seacocks & connections & found them good. The lignum vitae in stern tube has been renewed.*

*Examined the main boiler & steam dome and found them in a good condition.*

*Examined the Safety valves, slide valves, pumps and crankshaft & found them good.*

*The safety valves were found to blow at 75 lb per square inch*

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

*This vessel appears to be in a safe working condition and is in my opinion eligible to have the notification L.M.C. 8.84 recorded in the Register Book.*

Survey Fee (per Section 28) *1/9.84* £ *3* : *3* : —  
 Special Damage Fee (per Section 28) .. £ — : — : —  
 Certificate (if required) ..... £ : : —  
 Travelling Expenses (if chargeable) .... £ — : — : —

received by me,  
*4/9 1884*

*J.F.E.*

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUESDAY 2 SEPT 1884

Assigned

*L.M.C. 8.84*



Lloyd's Register  
 Foundation

LOW673-0204



It is submitted that this vessel is  
eligible to have the notification  
Lm 6. 8. 84 recorded the boilers  
being subject to resurvey as  
per Rule

DP  
27/8/84



© 2021

Lloyd's Register  
Foundation