

# REPORT of SURVEY for REPAIRS, &c.

(Received at London Office,

WEDNES. 3 DEC 1884

No.

No. in  
Reg. Book.

Survey held at

London

Date, First Survey

27 Nov

Last Survey

Nov 28 1884

692

on the Iron Screw

"Earl King"

(No. of Visits)

Master

Fiske

YEAR.

MONTH.

TONNAGE under Tonnage Deck

1583

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

2193

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

1418

Built at

Glasgow

When built

1865

— 9

Owners

W. Ross & Co

Port belonging to

Glasgow

Residence

By whom built

A. & J. Inglis

Destined Voyage

Neutral

If Surveyed Afloat or in Dry Dock

Pontoon

(State Name of Dock)

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Qr. Deck

ft.

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 44125 Port

Loc

Classed

100 A 1

REPAIRS, OR EXAMINATION AS PER RULE

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage to be separate from Repairs from other causes.)

Society's Freeboard (if assigned) as painted on Ship

in salt water

20 dw 103-8

in fresh water

State dates of any letters respecting this case

MOULDED DEPTH of Ship, if not yet recorded in Register Book

Survey for Condition

This vessel was placed in dry dock the bottom scraped cleaned and recoated. The starboard bottom plate frudder renewed. Several loose rivets renewed under counter.

Present Condition of the	Good	Good	Good
Decks	✓	✓	✓
Waterways	✓	✓	✓
Comings	✓	✓	✓
Upper Deck Beams & Fastenings	✓	✓	✓
Lower Deck Beams & Fastenings	✓	✓	✓
Planksheers	✓	✓	✓
Sheerstrakes	✓	✓	✓
Topsides	✓	✓	✓
Wales	✓	✓	✓
Plank (Bottom) and Counter	✓	✓	✓
Engine Room Skylights	✓	✓	✓
Coal Bunker, Openings, Lids, &c.	✓	✓	✓
Scuppers	✓	✓	✓
Cargo and Main Hatchways	✓	✓	✓
Hatches	✓	✓	✓
Treenails or Rivets	✓	✓	✓
Breasthooks and Stenson	✓	✓	✓
Transoms, Pointers, and Crutches	✓	✓	✓
Timbers of the Frame at the openings	✓	✓	✓
Ditto Ditto at other places	✓	✓	✓
Keelsons	✓	✓	✓
Clamps and Shelves	✓	✓	✓
Ceiling	✓	✓	✓
Rudder	✓	✓	✓
Copper (or Y.M.) When put on	✓	✓	✓
(State if on Felt.)	✓	✓	✓
Cement (if Iron Ship)	✓	✓	✓
Caulking of Bottom, Deck, & Waterways	✓	✓	✓
Windlass and Capstan	✓	✓	✓
Pumps	✓	✓	✓
Boats	✓	✓	✓
Masts, Yards, &c.	✓	✓	✓
Condition, how ascertained	✓	✓	✓
Sails	✓	✓	✓
Anchors No. of	✓	✓	✓
Cables	✓	✓	✓
Hawsers and Warps	✓	✓	✓
Standing & Running Rigging	✓	✓	✓

General Observations, Opinion as to Class, &c.

This vessel now appears to be in a sound and efficient condition eligible to be continued as classed

Entry or Registration Fee ...	£	:	:
(per Section 27, Scale I. or II.)			
Survey Fee (per Section 28) ...	£	:	:
Special Damage Fee (per Section 28) ...	£	:	:
* Certificate (if required) ...	£	:	:
Travelling Expenses (if any) ...	£	:	:
Second Surveyor's Fee (if any) ...	£	:	:

received by me,

188

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Character assigned

FRIDAY 13 DEC 1884

100 A 1



Lloyd's Register Foundation