

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

FRIDAY 6 FEB 1885

No.

No. in Survey held at London.

Date, first Survey Dec. 22 Last Survey Dec. 24 1885

Reg. Book.

169 on the Machinery of the S. S. "Mallard"

(Number of Visits 3)
Year Month

Tonnage, Gross 1621

Built at Newcastle

When built 1883-2

Ditto, Net 1054

Owners Persian Gulf S. N. Co.

Port belonging to London

Diameter of Cylinder 31 1/2

Engines made by H. Richardson & Co.

When made 1883

Length of Stroke 42

Boilers made by Do.

When made 1883

Pressure of Steam lbs.

If Surveyed Afloat or in Dry Dock Imhse. D. Dr.

Classed 100 A 1

Registered Horse Power 180

Last Survey No.

Port

L.M.C. 4-83.

Particulars of Repairs and Examination In Annual Survey.

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in dry dock, sea connections examined & found to be in good condition. Propeller & its connections sound & stem bush in good condition. New ring fitted on bush as guard for lignum vitae strips.

*It is submitted that
this vessel is eligible to
remain as classed
J.M. 6/2/85*

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

appears eligible to remain as classed.

Office or Registration Fee (per Sec. 27) £ : :
Survey Fee (per Section 28) £ : :
Special Damage Fee (per Section 28) £ : :
Certificate (if required) £ : :
Travelling Expenses (if chargeable) £ : :

received by me,
188


Geo. E. Wiseman.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUESDAY 10 FEB 1885

Assigned



Lloyd's Register
Foundation

LON674-0204