

18/2/85-
44636
REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

SATURDAY 14 FEB 1885

No.

No. in
Reg. Book.

Survey held at

London

Date, First Survey 26 Jan'y

Last Survey

Feb'y

1885

Master J. J. Melman

YEAR.

MONTH.

TONNAGE

NET 1188

GROSS 1227

UNDER DECK 1058

Built at

Hull

By whom

Samuelson

When 1868

Owners

New Zealand S. Co.

Port belonging to

Littleton

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Name of Dock Canal Dry Dock

Destined Voyage New Zealand

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Classed

Years assigned,
if a Wood Ship.

Character in
Register Book.

TA 1 12.83

SS Lon No 376

SS Lon No 181

Last Survey, No. 43347 Port Lon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed in Dry Dock the bottom cleaned and coated. A small portion of fore hold examined but not worth recording for SS No 2 as was recommended to be done being due. She had part of her outward cargo in when she came into dry dock and cargo waiting for shipment prevented, and the survey will be carried out on her return from her present voyage.

PRESENT CONDITION OF THE

Decks

Waterways

Comings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Engine Room Skylights

Plating

Plank (Bottom) & Counter

Treenails or Rivets

Breasthooks and Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at the openings

Ditto ditto at other places

Keelsons

Clamps & Shells

Ceiling

Rudder

Windlass & Capstan

Pumps

Cement (if Iron Ship)

Caulking of Bot'm, D'k, & Wat'rways

Copper, or Y.M. (State if on Felt.)

When put on

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 Nos. 2K

Cables Parton & Co

Hawsers & Warps

Standing & Running Rigging

Hatches

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo & Main Hatchways

General Observations, Opinion as to Class, &c.:

She is now in an efficient condition and respectfully recommend her to remain as classed and to have SS No 2 survey done on her return from her present voyage.

Samuelson Martin

Entry Fee (if chargeable) per Scale I., Sec. 27.

Office Fee (if chargeable) per Scale II., Sec. 27.

Survey Fee (per Section 28) 18/11/85

Special Damage Fee (if any) (per Sec. 28) 5

(if required). See margin.

Expenses (if chargeable)

Surveyor's Fee (if any)

received by me, 188

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 17 FEB 1885

Committee's Minute

Character assigned

Ranville



© 2021

Lloyd's Register
Foundation