

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, 20. 4. 85

No. in Reg. Book. 55 on the Tonnage:— NET 688 GROSS 1069

Survey held at London Date, First Survey ✓ Last Survey 11/4/85

Walton Iron Sew 87 Master Dargent

Built at Sunderland By whom Chort Bros When 1877-1

Owners A B Avery Port belonging to London

Owners' Address (if not already recorded in Appendix to Register Book.)

d Afloat or in Dry Dock afloat Name of Dock Surrey Con Destined Voyage Shields

Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.

Classed 100A1 Character in Register Book.

Last Survey, No. 18271 Port Shl

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water ft. ins. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship. in fresh water ft. ins. of any letters respecting this case. DD Shl 101-82

REPAIRS, OR EXAMINATION AS PER RULE

With reference to the attached memorandum stating that several pillars had been removed in the Chocas ceiling broken in fore hold which the owner promised to make the defects good on the vessel's return

I was advised upon my visit that the these repairs would be executed at Shields upon her arrival there, to which port she proceeds after unloading. I pointed out to the Captain by note that the special survey No 2 is due this year. also that the dingy required repair

PRESENT CONDITION OF THE	Good	Good	Good	Boats 2 repair good
Decks		Plank (Bottom) & Counter	Ceiling	Masts, Yards, &c.
Waterways		Treenails or Rivets	Rudder	Condition, how ascertained
Openings		Breasthooks & Stemson	Windlass & Capstan	Sails
Upper Dk. Beams & Fastenings		Transoms, Pointers, & Crutches	Pumps	Anchors No. of
Lower Dk. Beams & Fastenings		Timbers of Frame at the openings	Cement (if Iron Ship)	Cables
Plank sheers		Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Hawsers & Warps
Sheerstrakes		Keelsons	Copper, or Y.M. (State if on Felt.)	Standing & Running Rigging
Topsides		Clamps & Shelves	When put on	Hatches
Wales				
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.	Scuppers	
			Cargo & Main Hatchways	

General Observations, Opinion as to Class, &c.:

These repairs should be notified to the Society's Surveyors at Newcastle. The vessel appears as far as was seen to be in a sound and efficient condition eligible in my opinion to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27. £ : :
Office Fee (if chargeable) per Scale II., Sec. 27. £ : :
Survey Fee (per Section 28) £ : :
Age Fee (if any) (per Sec. 28) £ : :
Insured. See margin £ : :
As (if chargeable) £ : :
Fee (if any) £ : :

received by me, 188

Edward John Tierney
Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 21 APRIL 1885

Com.tee's Minute

Character assigned

22/4/85

EDMUND TAYLOR & SON, Commercial Steam Printers, 18, Old Street, Goswell Road, London.

Lloyd's Register Foundation

LON 574-0484